



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FWD SINGAPORE PTE LTD

Ref : CS3/FWD20005184/Etf3e2-1

6 TEMASEK BOULEVARD
#18-01 SUNTEC TOWER 4 SINGAPORE 038986

Date : 16-06-2020



Code : FWD

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLZ 8820T	Veh. Inspected	SKG 160D
Policy No.	PNPV2019-0000376101	Coverage (\$)	0.00
Claim No.	1202000016273	Excess (\$)	0.00
Assign From	JOSEY LOH	Assign Date	15/06/2020

2. Vehicle Particulars & Condition

Make & Model	BMW X1	c.c	1997
Engine No.	HIDDEN	Year of Reg.	2012
Chassis No.	WBAVL92070VL60574	Colour	BLACK
Odometer	80509	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/45 R18	PIRELLI	5 mm
L/H Front Tyre	225/45 R18	PIRELLI	5 mm
R/H Rear Tyre	225/45 R18	PIRELLI	5 mm
L/H Rear Tyre	225/45 R18	PIRELLI	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	11/04/2020	Inspection Date	14/04/2020
Survey held at	PAUL HOE BATTERIES & MOTOR SERVICES BLK 1 KAKI BUKIT AVE 6 #01-109 AUTOBAY SINGAPORE 417833		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------