

Veron Chen (LKKAUTO)

From: Simon Ho (LKKAUTO)
Sent: Tuesday, 9 June 2020 9:56 AM
To: Veron Chen (LKKAUTO)
Cc: Rasul (LKKAUTO)
Subject: Re: FBD 2159T

Dear Veron,

Audit check done for FBD2159T found repair range \$1,500 to \$2,000 is more closer.

Best Regards,

Simon Ho

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: simonho@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

From: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Sent: Tuesday, 9 June 2020 9:35 AM
To: Simon Ho (LKKAUTO) <SimonHo@lkkauto.com>
Subject: FBD 2159T

Dear Simon,

File for audit check.

Photos in Merimen system.

Repair range \$1000-\$2000/ 3 days

Note: We are on work from home arrangement. All correspondence should be made via email. Submission of claim related documents will be in softcopy. Any inconvenience caused is much regretted.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)