

**Shirley Hiew (LKK Auto)**

---

**From:** Simon Ho (LKKAuto)  
**Sent:** Monday, 29 June 2020 6:05 pm  
**To:** Shirley Hiew (LKK Auto)  
**Subject:** Re: SLJ 2595S DOA - 03/06/2020

Hi Shirley,

Audit check done for SLJ2595S, found the rim is too high and the undercarriage unlikely to be damaged as this accident happen in car park. I already spoken to Taufikh to look into it again.

Best Regards,

**Simon Ho**

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561| email: [simonho@lkkauto.com](mailto:simonho@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



*Save the Earth. Print only when necessary.*

---

**From:** Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>  
**Sent:** Monday, 29 June 2020 3:57 PM  
**To:** Simon Ho (LKKAuto) <SimonHo@lkkauto.com>  
**Subject:** SLJ 2595S DOA - 03/06/2020

Hi Simon,

Kindly check the TP report and let me know whether can I submit this report.

Documents uploaded in Views.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Sur@lkkauto.com](mailto:Sur@lkkauto.com) | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**Note: We are on work from home arrangement. All correspondence should be made via email. Submission of claim related documents will be in softcopy. Any inconvenience caused is much regretted.**