

Advant Auto Garage Pte Ltd

SLJ2595S Audi A1

Accident along: Bukit Batok East Ave. 3

S/N	Qty	Description	(S\$)
Parts			
1	1pcs	Front bumper	\$ 1,300.00
2	2pcs	Front bumper side retainer @38/pcs	\$ 176.00
3	1pcs	Rh headlamp	\$ 950.00
4	1pcs	Front rh fender	\$ 490.00
5	1pcs	Front rh fender inner shield	\$ 225.00
6	1pcs	Front rh rim	\$ 1,500.00
7	1pcs	Front rh shock absorber	\$ 210.00
8	1pcs	Front rh knuckle arm	\$ 390.00
9	1pcs	Front rh lower arm	\$ 230.00
10	1pcs	Anti-roll bar	\$ 105.00
11	1pcs	Rh anti roll bar link	\$ 68.00

de ✓
Rt arm ✓ 38
cut ✓
RX
de ✓
dA ✓
bt ✓
bt ✓
bt ✓
X nn
X nn

Total \$ 5,544.00 4843
-10% \$ 554.40
Parts Sub Total \$ 4,989.60 4358.70

Labour			
1		Towing	\$ 100.00
2		To check wiring sytsem	\$ 80.00
3		To reset and programe after repair.	\$ 350.00
4		To r&r front rh undercarriage.	\$ 250.00
5		To conduct wheel alignment.	\$ 120.00
6		To R&R fornt bumper, rh headlamp, front rh fender and attachements.	\$ 500.00
7		To respray on font fender , front bumper, front rh door and accident affected area.	\$ 800.00
8		Rust proofinng	\$ 80.00
Labour Total:			\$ 2,280.00
Sub Total (labour and parts):			\$ 7,269.60

towing receipt XNN
30
150
120
80 need the * alignment report
350
450
30
1210

Vehicle is at 50 Bukit Batok Street 23, #01-15, Singapore 659578

4358.70
1210
TOTAL 5568.70
L/S \$4450
5 DAYS

Taufik 97495749
WP 05 days
Lumpsum
Resurvey after repair
taufik@tkkauto.com