

Advant Auto Garage Pte Ltd

SLJ2595S Audi A1

Accident along: Bukit Batok East Ave. 3

S/N	Qty	Description	(S\$)	
Parts				
1	1pcs	Front bumper	\$ 1,300.00	de ✓ 1125.60
2	2pcs	Front bumper side retainer @38/pcs	\$ 76.00	Rt/orn ✓ 38
3	1pcs	Rh headlamp	\$ 950.00	cut ✓
4	1pcs	Front rh fender	\$ 490.00	RX
5	1pcs	Front rh fender inner shield	\$ 225.00	de ✓
6	1pcs	Front rh rim	\$ 1,500.00	da ✓ 1000
7	1pcs	Front rh shock absorber	\$ 210.00	X bt ✓
8	1pcs	Front rh knuckle arm	\$ 390.00	bt ✓
9	1pcs	Front rh lower arm	\$ 230.00	bt ✓
10	1pcs	Anti-roll bar	\$ 105.00	X nn
11	1pcs	Rh anti roll bar link	\$ 68.00	X nn
Total			\$ 5,544.00	4168.60
-10%			\$ 554.40	
Parts Sub Total			\$ 4,989.60	3751.74

Labour				
1		Towing	\$ 100.00	towing receipt x nn
2		To check wiring sytsem	\$ 80.00	30
3		To reset and programe after repair.	\$ 350.00	150
4		To r&r front rh undercarriage.	\$ 250.00	120
5		To conduct wheel alignment.	\$ 120.00	80 need the * alignment report
6		To R&R fornt bumper, rh headlamp, front rh fender and attachements.	\$ 500.00	350
7		To respray on font fender , front bumper, front rh door and accident affected area.	\$ 800.00	450
8		Rust proofinng	\$ 80.00	30
Labour Total:			\$ 2,280.00	1210
Sub Total (labour and parts):			\$ 7,269.60	4961.74 L/S\$4000

Vehicle is at 50 Bukit Batok Street 23, #01-15, Singapore 659578

Taufik 97495749
WP 05 days
Lumpsum
Resurvey after repair
taufik@tkkauto.com