



To: AIG Insurance Pte Ltd

12th June 2020

Attn : Motor Property Claims

Dear Sir,

Accident Involving SJJ-3207-E & SLD-6702-E (09th June 2020)

Quotation for the repair of Vehicle Number SJJ-3207-E


No	Description	Price
1	1 Piece Rear Bumper / CR4	\$ 680.00 ✓
2	2 Pieces Rear Bumper Side Retainers / BR	\$ 68.00 ✓
3	1 Piece Rear Bumper Clips / Nec	\$ 6.00 ✓
4	2 Pieces Rear Bumper Reflectors X SVC.	\$ 85.00 X
5	1 Piece Rear Panel / bp	\$ 280.00 ✓
6	1 Piece Rear Panel Garnish / CR4	\$ 120.00 ✓
7	1 Piece Rear Panel Clips / Nec	\$ 15.00 ✓
8	2 Pieces Tail Lamp / CRA	\$ 560.00 ✓
9	2 Pieces Clips / Nec	\$ 15.00 ✓
10	1 Piece Rear Boot BP / bp	\$ 580.00 ✓
11	1 Piece Rear Boot Rubber / CR4	\$ 130.00 ✓
12	1 Piece Rear Boot Lock / Jem	\$ 160.00 ✓
13	1 Piece Rear Boot Latch X SVC	\$ 85.00 X
14	1 Piece Rear Boot Logo / Nec	\$ 58.00 ✓
15	2 Pieces Rear Boot Hinges / BT	\$ 120.00 ✓
16	1 Piece Spare Tyre Sponge (RH) ? X SVC	\$ 60.00 X
17	1 Piece Spare Tyre Sponge (LH) ? X SVC	\$ 60.00 X
18	1 Piece Panel Sealant / Nec	\$ 100.00 40

19	2 Pieces Reverse Sensor /short	\$ 300.00	200
20	Rear Skirting /CRA	\$ 165.00	
21	Spoiler X svc. svc.	\$ 145.00	
Total		\$ 3792.00	3,197.00
Less 25 %		\$ 948.00	- 25%
Total		\$ 2844.00	2,897.75

1	Labour Charge Panel Beating	\$ 890.00	800
2	Spray Painting	\$ 900.00	800
3	Rust Proofing	\$ 120.00	50
4	Transfer Rear Boot Attachments	\$ 100.00	40
Total		\$ 4854.00	1,640.00

In Singapore Dollars: FOUR THOUSAND, EIGHT HUNDRED AND FIFTY FOUR DOLLARS ONLY

Mohamed Automobile



Repair dy: - 4 days

L/S.

After paint photo

Sun Pin (Lkh)

12/06/2020

TP without photo

~~Sunpin @ photo~~

Sunpin @ lkkauto.com

8661 2627

P = 2,397.75

L = 1,640

4,087.75

- 20%

3,270.20

L/S

\$ 3,250

4 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: