

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 36840

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0416/2020/NS
Date : 8-Jun-20

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mdm Tan Lay Geok
Address : 7 Lentor Street
Singapore 786753
Telephone : HP +65 98263801
Type of Claim : Own Damage Claims
Policy No. : 2100420155-04
Vehicle No : **SKS 6878 P**
Model Code : Audi A6 1.8 TFSI ULTRA S
Model / Year : 29/4/2015
Engine No : CYG 003599
Chassis No : WAUZZZ4G0FN065593
Mileage : 4500
Date In : 8-Jun-20
Estimated By : Johnny Boo / Allan Wu
Accident Date : 6-Jun-20
Place of Accident : Sembawang Road And Jalan Mata Ayer Junction

Premium Automobiles

55, Ubi Road 1, Singapore 408699
Tel: 6366 7121 Fax: 6841 1181

Telefax

Estimated Labour Charges for Accident Vehicle. SKS 6878 P

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00 ✓	✓
2	To remove and renew aircon condenser, charged air cooler, radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N \$ 1,400.00 ?	✗
3	To dismantle and renew front bumper, rhs front fender, bonnet, and rhs headlight. To renew front lock carrier and align to position. Re-organise crash management components. Reinstall all parts removed.	\$ 6,000.00	✓ 1000 (Without Lock Carrier) 2250 (With Lock Carrier)
4	To respray front bumper, rhs front fender and bonnet. ✓	\$ 3,600.00	✓ 1100
5	To carry out diagnostic check.	S/N \$ 192.00 ✓	✓
TOTAL LABOUR CHARGES		: <u>\$ 11,480.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKS 6878 P

S/N	Parts Description	Damaged Parts & Prices		
		S/Nett	Remarks	
1	FRONT BUMPER <i>Discolored</i>	\$ 2,634.00 ✓	2107.20	
2	FRONT BUMPER GRILLE <i>cut</i>	\$ 619.00 ✓	495.20	
3	LOCKING CLIP ? NN	18 \$ 67.00 ? X		
4	FRONT BUMPER TRIM ? NN	\$ 286.00 ? X		
5	FRONT BUMPER FIXING PARTS <i>new</i>	\$ 45.00 X		
6	FRONT BUMPER CLOSING ELEMENT ? cracked	\$ 206.00 ? ✓	164.80	
7	FRONT BUMPER SPOILER ? NN	\$ 234.00 ? X		
8	RADIATOR GRILLE <i>cracked</i>	\$ 1,820.00 ✓	1456.00	
9	RADIATOR GRILLE COVER ? NN	\$ 34.00 ? X		
10	RADIATOR GRILLE SENSOR SUPPORT - LH / RH FRONT ? NN	\$ 126.00 ? X		
11	FRONT BUMPER AIR GUIDE GRILLE - RH <i>missing</i>	\$ 331.00 ✓	264.40	
12	FRONT BUMPER AIR GUIDE GRILLE COVER - RH <i>Defy d</i>	\$ 48.00 ✓	38.32	
13	FRONT WHEEL SPOILER - RH <i>after cracked</i>	\$ 249.00 X ✓	199.20	
14	FRONT BUMPER SIDE REINFORCEMENT BEAM ? NN	\$ 778.00 ? X		
15	FRONT BUMPER FOAM FILLER PIECE <i>cracked</i>	\$ 223.00 ✓	178.40	
16	FRONT BUMPER GUIDE PIECE - RH <i>new</i>	\$ 36.00 X.		
17	FRONT BUMPER COVER <i>Def d</i>	\$ 116.00 ✓	92.40	
18	FRONT BUMPER BRACKET HOLDER - RH ? NN	\$ 245.00 ? X		
19	AIRCON STICKER <i>new</i>	NEC \$ 18.00 ✓	14.40	
20	CAUTION SIGN STICKER <i>new</i>	NEC \$ 13.00 ✓	10.24	
SUB TOTAL SPARE PARTS		: \$ 8,128.00		

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKS 6878 P

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
21	SIGNAL HORN - HIGH TONE RH <i>2 new</i>	\$ 221.00	+
22	SPRING SHACKLE - RH	\$ 44.00	+
23	FRONT PARKING AID SENSOR - INNER / OUTER <i>2 NN</i>	TBC	? X
24	FRONT BUMPER WIRING SET <i>new</i>	\$ 544.00	+
25	FRONT FENDER - RH <i>new</i>	\$ 1,310.00	+
26	FRONT FENDER ATTACHMENT PARTS <i>2</i>	\$ 97.00	+
27	STONE GUARD FILM - RH <i>new</i>	\$ 114.00	+
28	FRONT FENDER BRACE - RH	\$ 90.00	+
29	WHEEL HOUSING LINER - RH	\$ 259.00	+
30	WHEEL HOUSING LINER ATTACHMENT PARTS <i>2 new</i>	\$ 69.00	+
31	FRONT STONE CHIP GUARD - RH	\$ 68.00	+
32	ADHESIVE TAPE <i>2 NN</i>	\$ 52.00	? X
33	BONNET <i>Dented.</i>	\$ 5,119.00	✓ 4095.20
34	BONNET ATTACHMENT PARTS <i>2 new</i>	\$ 168.00	+
35	BONNETR LID HINGE - LH / RH	\$ 304.00	+
36	GAS FILLED STRUT <i>2</i>	\$ 224.00	+
37	BONNET LOCK BAR	\$ 94.00	+
38	BONNET CATCH HOOK <i>new</i>	\$ 17.00	+
39	BONNET LID LOCK	\$ 403.00	+
40	HEADLIGHT MOUNTING - RH <i>2 NN</i>	\$ 112.00	? X
SUB TOTAL SPARE PARTS		: \$ 9,309.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKS 6878 P

S/N	Parts Description	Damaged Parts & Prices		Remarks
		S/Nett		
41	LED HEADLIGHT - RH ? NN	\$	11,672.00	? X
42	LIFT CYLINDER - RH <i>new</i>	\$	223.00	*
43	LOCK CARRIER ? NN	\$	1,174.00	? X
44	AIRCON CONDENSER	\$	712.00	*
45	CHARGE AIR COOLER	\$	529.00	*
46	PRESSURE HOSE - RH	\$	336.00	*
47	RADIATOR	\$	791.00	*
48	RADIATOR RUBBER BUSH - UPPER	2 \$	13.00	*
49	RADIATOR RUBBER BUSH - CENTRE	2 \$	19.00	*
50	RADIATOR RUBBER BUSH - LOWER	2 \$	25.00	*
51	COOLANT CONCENTRATE	4 \$	137.00	*
52	RADIATOR TWIN FAN RING	\$	247.00	*
53	RADIATOR FAN	\$	837.00	*
54	RADIATOR FAN	\$	722.00	*
55	RADIATOR AIR GUIDE - RH	\$	27.00	*
56	RADIATOR COVER - UPPER CENTRE	\$	28.00	*
57	RADIATOR SEALING STRIP	\$	21.00	*
58	BONNET CATCH HOOK	\$	132.00	*
59	FRONT NO PLATE <i>Best</i>	S/N \$	60.00	✓ 60.00
60	SUNDRIES ? Nec	\$	400.00	✓ 38.24
TOTAL SPARE PARTS		:	\$ 35,542.00	
TOTAL LABOUR CHARGES		:	\$ 11,480.00	
GRAND TOTAL		:	\$ 47,022.00	

All charges are not inclusive of GST.
Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

47,044.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel 6366 2323 Fax 6841 1183

Telefax

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Name

: Adrian Lim
: 09/06/20 J

Surveyed Date

Authorised Date

Excess Cost

Liability

Remarks

: Not Authorised, 05 Days (Without Lacc Carrier)
: 08 Days (With Lacc Carrier)

Please Note

: This estimate is based on visual inspection of the affected vehicle
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.

For inspection of vehicle, please refer to Ms Norah Khai at

Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo

Body Repair Manager

Allan Wu

Claims Consultant