

Car-in 11/6/2020

Krum / Harvey
wp: 36840

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 3323 Fax: 6841 1185

Telefax

Material List for Accident Vehicle Regn No. SKS 6878 P

S/N	Parts Description	Damaged Parts & Prices		Remarks
		S/Nett		
1	FRONT BUMPER <i>Dislodged</i>	\$	2,634.00	✓
2	FRONT BUMPER GRILLE <i>cut</i>	\$	619.00	✓
3	LOCKING CLIP	18 \$	67.00	?
4	FRONT BUMPER TRIM	\$	286.00	?
5	FRONT BUMPER FIXING PARTS <i>Neu</i>	\$	45.00	✓
6	FRONT BUMPER CLOSING ELEMENT <i>CR</i>	\$	206.00	?
7	FRONT BUMPER SPOILER	\$	234.00	?
8	RADIATOR GRILLE <i>cracked</i>	\$	1,820.00	✓
9	RADIATOR GRILLE COVER	\$	34.00	✓
10	RADIATOR GRILLE SENSOR SUPPORT - LH / RH FRONT	2 \$	126.00	?
11	FRONT BUMPER AIR GUIDE GRILLE - RH <i>Missing</i>	\$	331.00	✓
12	FRONT BUMPER AIR GUIDE GRILLE COVER - RH <i>Destroyed</i>	\$	48.00	✓
13	FRONT WHEEL SPOILER - RH <i>see in CR</i>	\$	249.00	✓
14	FRONT BUMPER SIDE REINFORCEMENT BEAM	\$	778.00	?
15	FRONT BUMPER FOAM FILLER PIECE <i>cracked</i>	\$	223.00	✓
16	FRONT BUMPER GUIDE PIECE - RH <i>see in CR</i>	\$	36.00	✓
17	FRONT BUMPER COVER <i>Del</i>	\$	116.00	✓
18	FRONT BUMPER BRACKET HOLDER - RH	\$	245.00	?
19	AIRCON STICKER <i>Neu</i>	NEC \$	18.00	✓
20	CAUTION SIGN STICKER <i>Neu</i>	NEC \$	13.00	✓
SUB TOTAL SPARE PARTS		:	\$	8,128.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKS 6878 P

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
41	LED HEADLIGHT - RH ?	\$ 11,672.00	
42	LIFT CYLINDER - RH <i>Ref an</i>	\$ 223.00	
43	LOCK CARRIER ?	\$ 1,174.00	
44	AIRCON CONDENSER	\$ 712.00	
45	CHARGE AIR COOLER	\$ 529.00	
46	PRESSURE HOSE - RH	\$ 336.00	
47	RADIATOR	\$ 791.00	
48	RADIATOR RUBBER BUSH - UPPER	2 \$ 13.00	
49	RADIATOR RUBBER BUSH - CENTRE	2 \$ 19.00	
50	RADIATOR RUBBER BUSH - LOWER	2 \$ 25.00	
51	COOLANT CONCENTRATE	4 \$ 137.00	
52	RADIATOR TWIN FAN RING	\$ 247.00	
53	RADIATOR FAN	\$ 837.00	
54	RADIATOR FAN	\$ 722.00	
55	RADIATOR AIR GUIDE - RH <i>ca</i>	\$ 27.00	
56	RADIATOR COVER - UPPER CENTRE	\$ 28.00	
57	RADIATOR SEALING STRIP	\$ 21.00	
58	BONNET CATCH HOOK	\$ 132.00	
59	FRONT NO PLATE <i>Best</i>	S/N \$ 60.00	
60	SUNDRIES	\$ 400.00	
TOTAL SPARE PARTS		\$ 35,542.00	
TOTAL LABOUR CHARGES		\$ 11,480.00	
GRAND TOTAL		\$ 47,022.00	

All charges are not inclusive of GST

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett

temporarie *renew* *back*

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Estimate No.

Date

Service Advisor

Pages

Regn No

Model No

PA/OD/0416/2020/NS

11-Jun-20

Glory Tan

1 of 1

SKS 6878 P

Audi A6 1.8 TFSI ULTRA S

Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	Temperature sensor bracket <i>cond</i>	\$ 22.00	
TOTAL		\$ 22.00	

Rane

11/06/2020

Subject to

insurance approval

For Premium Automobiles Pte Ltd

Authorised Signature