

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1193

Telefax

Material List for Accident Vehicle Regn No. SKS 6878 P

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
21	SIGNAL HORN - HIGH TONE RH?	\$ 221.00	
22	SPRING SHACKLE - RH	\$ 44.00	
23	FRONT PARKING AID SENSOR - INNER / OUTER ? 2	TBC	
24	FRONT BUMPER WIRING SET	\$ 544.00	
25	FRONT FENDER - RH	\$ 1,310.00	
26	FRONT FENDER ATTACHMENT PARTS	\$ 97.00	
27	STONE GUARD FILM - RH	\$ 114.00	
28	FRONT FENDER BRACE - RH	\$ 90.00	
29	WHEEL HOUSING LINER - RH	\$ 259.00	
30	WHEEL HOUSING LINER ATTACHMENT PARTS	\$ 69.00	
31	FRONT STONE CHIP GUARD - RH	\$ 68.00	
32	ADHESIVE TAPE	\$ 52.00	
33	BONNET	\$ 5,119.00	Approved replace Bonnet by Adrian 9/6/2020
34	BONNET ATTACHMENT PARTS	\$ 168.00	
35	BONNETR LID HINGE - LH / RH 2	\$ 304.00	
36	GAS FILLED STRUT 2	\$ 224.00	
37	BONNET LOCK BAR 2	\$ 94.00	
38	BONNET CATCH HOOK	\$ 17.00	
39	BONNET LID LOCK 2	\$ 403.00	
40	HEADLIGHT MOUNTING - RH ?	\$ 112.00	
SUB TOTAL SPARE PARTS		: \$ 9,309.00	