

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Estimate No.

PA/OD/0416/2020/NS

Date

11-Jun-20

Service Advisor

Glory Tan

Pages

1 of 1

Regn No

SKS 6878 P

Model No

Audi A6 1.8 TFSI ULTRA S

Quantity	Description	Unit Price	Amount
<u>Parts</u> 1	Temperature sensor bracket <i>crash</i>	\$ 22.00	
TOTAL		\$ 22.00	

For Premium Automobiles Pte Ltd

Ram
11/06/2020

Authorised Signature

*Subject to
insurance approval*

Car-in 11/6/2020

Kram / Hovey

wp: 36840

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2123 Fax: 6841 1151

Telefax

Material List for Accident Vehicle Regn No. SKS 6878 P

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER <i>Replaced</i>	\$ 2,634.00	✓
2	FRONT BUMPER GRILLE <i>at</i>	\$ 619.00	✓
3	LOCKING CLIP ?	18 \$ 67.00	?
4	FRONT BUMPER TRIM ?	\$ 286.00	?
5	FRONT BUMPER FIXING PARTS <i>New</i>	\$ 45.00	✓
6	FRONT BUMPER CLOSING ELEMENT ? <i>crack</i>	\$ 206.00	?
7	FRONT BUMPER SPOILER ?	\$ 234.00	?
8	RADIATOR GRILLE <i>crack</i>	\$ 1,820.00	✓
9	RADIATOR GRILLE COVER ?	\$ 34.00	
10	RADIATOR GRILLE SENSOR SUPPORT - LH / RH FRONT ?	2 \$ 126.00	?
11	FRONT BUMPER AIR GUIDE GRILLE - RH <i>Missing</i>	\$ 331.00	✓
12	FRONT BUMPER AIR GUIDE GRILLE COVER - RH <i>Replaced</i>	\$ 48.00	✓
13	FRONT WHEEL SPOILER - RH <i>new crack</i>	\$ 249.00	✓
14	FRONT BUMPER SIDE REINFORCEMENT BEAM ?	\$ 778.00	?
15	FRONT BUMPER FOAM FILLER PIECE <i>crack</i>	\$ 223.00	✓
16	FRONT BUMPER GUIDE PIECE - RH <i>new</i>	\$ 36.00	✓
17	FRONT BUMPER COVER <i>Replaced</i>	\$ 116.00	✓
18	FRONT BUMPER BRACKET HOLDER - RH ?	\$ 245.00	?
19	AIRCON STICKER <i>new</i>	NEC \$ 18.00	✓
20	CAUTION SIGN STICKER <i>new</i>	NEC \$ 13.00	✓
SUB TOTAL SPARE PARTS		: \$ 8,128.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKS 6878 P

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
21	SIGNAL HORN - HIGH TONE RH?	\$ 221.00	+
22	SPRING SHACKLE - RH	\$ 44.00	+
23	FRONT PARKING AID SENSOR - INNER / OUTER ? 2	TBC	?
24	FRONT BUMPER WIRING SET	\$ 544.00	+
25	FRONT FENDER - RH	\$ 1,310.00	+
26	FRONT FENDER ATTACHMENT PARTS	\$ 97.00	+
27	STONE GUARD FILM - RH	\$ 114.00	+
28	FRONT FENDER BRACE - RH	\$ 90.00	+
29	WHEEL HOUSING LINER - RH	\$ 259.00	+
30	WHEEL HOUSING LINER ATTACHMENT PARTS	\$ 69.00	+
31	FRONT STONE CHIP GUARD - RH	\$ 68.00	+
32	ADHESIVE TAPE	\$ 52.00	?
33	BONNET	\$ 5,119.00	+
34	BONNET ATTACHMENT PARTS	\$ 168.00	+
35	BONNET LID HINGE - LH / RH 2	\$ 304.00	+
36	GAS FILLED STRUT 2	\$ 224.00	+
37	BONNET LOCK BAR 2	\$ 94.00	+
38	BONNET CATCH HOOK	\$ 17.00	+
39	BONNET LID LOCK 2	\$ 403.00	+
40	HEADLIGHT MOUNTING - RH ?	\$ 112.00	?
SUB TOTAL SPARE PARTS		: <u>\$ 9,309.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKS 6878 P

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
41	LED HEADLIGHT - RH ?	\$ 11,672.00	
42	LIFT CYLINDER - RH <i>not in</i>	\$ 223.00	
43	LOCK CARRIER ?	\$ 1,174.00	
44	AIRCON CONDENSER	\$ 712.00	
45	CHARGE AIR COOLER	\$ 529.00	
46	PRESSURE HOSE - RH <i>not in</i>	\$ 336.00	
47	RADIATOR	\$ 791.00	
48	RADIATOR RUBBER BUSH - UPPER	2 \$ 13.00	
49	RADIATOR RUBBER BUSH - CENTRE	2 \$ 19.00	
50	RADIATOR RUBBER BUSH - LOWER	2 \$ 25.00	
51	COOLANT CONCENTRATE	4 \$ 137.00	
52	RADIATOR TWIN FAN RING	\$ 247.00	
53	RADIATOR FAN	\$ 837.00	
54	RADIATOR FAN	\$ 722.00	
55	RADIATOR AIR GUIDE - RH <i>OK</i>	\$ 27.00	
56	RADIATOR COVER - UPPER CENTRE	\$ 28.00	
57	RADIATOR SEALING STRIP	\$ 21.00	
58	BONNET CATCH HOOK	\$ 132.00	
59	FRONT NO PLATE <i>Best</i>	S/N \$ 60.00	
60	SUNDRIES ?	\$ 400.00	
TOTAL SPARE PARTS		: \$ 35,542.00	
TOTAL LABOUR CHARGES		: \$ 11,480.00	
GRAND TOTAL		: \$ 47,022.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

temporary sensor bracket

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Ling
Surveyed Date : 09/06/20
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 05 Days (Without Lock Carrier)
08 Days (With Lock Carrier)

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant