

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 35695

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0389/2020/NS
Date	:	12-May-20

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Ms Sayaka Okano Dayal
Address	:	5 Ocean Way #04-14 Singapore 098369
Telephone	:	(HP) 81013905
Type of Claim	:	Own Damage Claim
Policy No.	:	2070058594
Vehicle No	:	SMT 1725 B
Model Code	:	Audi Q3 1.4 TFSI S TRONIC
Model / Year	:	Mar-20
Engine No	:	CZD 892043
Chassis No	:	WAUZZZF35L1081981
Mileage	:	-
Date In	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	11-May-20
Place of Accident	:	5 Ocean Way W Residences Carpark

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMT 1725 B

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
1	To remove and transfer rear parking aid and rear lid kick sensor. Check function and renew according to damage.	S/N \$ NN	360.00	X
2	To renew rhs 1/4 glass to facilitate fender renewal.	S/N \$	300.00	✓ 300.00
3	To install solar film for 1/4 glass.	S/N \$	400.00	✓ 400.00
4	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and audio equipment.	S/N \$	1,400.00	✓ 1400.00
5	To remove and reinstall rear seat, back rest, hat tray, abcd pillar trims, luggage compartment trims. Dislodge roof liner and disengage curtain airbag etc.	S/N \$	1,400.00	✓ 1400.00
SUB TOTAL LABOUR CHARGES		:	<u><u>\$ 3,860.00</u></u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMT 1725 B

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
6	To remove and transfer rhs rear door's multi-lock system and power window devices. Inspect for damages.	S/N \$ 280.00	✓
7	To dismantle rear bumper and rhs rear door. Cut out and weld rhs rear fender. To renew rhs rear door. Re-organise crash management components and reinstall all parts removed.	\$ 6,400.00	3000 3500
8	✓ To respray rhs rear door, door handle, rhs rear fender, rhs sill panel, door entrances, roof channel, drain panel and end panelling. To carry out stone chip treatment and joint sealer works.	4 panel + handle 2575 ✓ \$ 5,700.00	4.5 x 550 = 2475 Handle = 100
9	To renew rhs rear rim and carry out wheel alignment.	S/N \$ 280.00	✓
10	To carry out diagnostic check.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 16,712.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SMT 1725 B

S/N	Parts Description	Damage Parts & Prices		
		S/Nett		Remarks
1	REAR SIDE PANEL - RH <i>Dented</i>	\$	3,052.00 ✓	2441.60
2	SIDE WINDOW - RH <i>New</i>	\$	577.00 ✓	461.60
3	REAR DOOR - RH <i>Dented</i>	\$	2,512.00 ✓	2009.60
4	REAR DOOR OUTER SEAL- RH <i>New</i>	NEC \$	127.00 ✓	101.60
5	REAR DOOR ATTACHMENT PARTS <i>New</i>	\$	293.00 ✗	
6	REAR DOOR CATCH <i>New</i>	\$	113.00 ✗	
7	REAR DOOR COVER - RH REAR <i>cut</i>	\$	242.00 ✓	193.20
8	EXTERIOR DOOR HANDLE - RH <i>Regis</i>	\$	190.00 ✗	
9	DOOR HANDLE HOUSING - RH <i>Regis</i>	\$	26.00 ✗	
10	REAR MOUNTING BAR <i>New</i>	\$	154.00 ✗	
11	BOWDEN CABLE <i>New</i>	\$	50.00 ✗	
12	REAR WHEEL COVER - LH / RH <i>New</i>	2 \$	506.00 ✓	404.80
13	REAR ALUMINIUM RIM - RH <i>New</i>	\$	720.00 ✗	
14	ACRYLIC SEALANT <i>per</i>	S/N \$	180.00 ✓	180.00
15	CAVITY WAX	S/N \$	140.00 ✓	140.00
16	STONE CHIP	S/N \$	180.00 ✓	180.00
17	METAL FILLER POWDER <i>per</i>	S/N \$	280.00 ✓	280.00
18	1/4 GLASS SEALANT	S/N \$	100.00 ✓	100.00
19	SUNDRIES <i>New</i>	\$	400.00 ✓	110.24

TOTAL SPARE PARTS CHARGES	:	\$ 9,842.00
TOTAL LABOUR CHARGES	:	\$16,712.00
GRAND TOTAL	:	\$26,554.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lim
Surveyed Date : 09/06/20
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 13 days -

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel: (65) 6366 2323 Fax: (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0389/2020/NS 3-Jul-20 Glory Tan 1 of 1 SMT 1725 B Audi Q3 1.4 TFSI S TRONIC
Quantity	Description	Unit Price	Amount
<u>Parts</u> 1	Rear end panelling outer DETA Nec.	\$ 293.00	234.40
<u>Labours</u> 1	To cut out rear end panelling outer.	\$ 3,200.00	1000 750.00
TOTAL		\$ 3,493.00	

For Premium Automobiles Pte Ltd

Authorised Signature

Adrian Ling

07/07/20

slg

Add 2 days
of repairs.