

ASSIGNMENT

From:

Estimated Cost:

Date:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

816k

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

06

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

30/4

GIA & Est not ready
GIA will email over
11pm & 38000 to submit

Date/Time, File Pass to?

☐

: Prell. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S - RS - SI

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

Veh No:

STY 863B

Yr Regn:

07, 10

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy wish

c.c

1797

Colour

M. Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

208058

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

86820

0015873

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD / Rlm or

Tyre Size:

F:

195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal.

8

mm

Rear

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

21/4/20

D.O.I.

30/4/2020

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
1st ds & 2nd N/S

The U/C / Chassis frame / Body Structure affected due to collision.

威利摩哆 WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,
SINGAPORE 575644.
TEL: 6456 9830 • FAX: 6458 0128 • EMAIL: weileemotorworks@gmail.com
Business Regn No: 269436/00J

30, APR 2020

Wei Lee Motor Works Motor
9 Sin Ming Industries
#01-32

Dear Sir,

Estimate cost of repair for vehicle no: SJY863B

Not Authorized
11 Smp & 3800h Max
Presumy After Paint
6 days

To supply--

Description	Qty	Amount	
Bonnet	1	698.80	✓
Bonnet hinge @51.30	2	102.60	X
Headlamp @833.70	2	1,667.40	✓
Headlamp lower bracket	2		
Front bumper	1	594.90	✓
Front bumper enforcement	1	275.20	✓
Front bumper sponge		81.60	✓
Front bumper retainer @55.30	2	110.60	✓
Front support panel	1	1,179.80	✓
Front grille	1	162.75	✓
Front grille clip		21.00	✓
Front bumper foglamp cover @49.40	2	98.80	✓
Radiator	1	1,608.30	✓
Air con condenser	1	1,404.30	✓
Fan cowling	1	200.70	X
Fan motor @550	2	1,100.00	X
Fan blade @165.20	2	330.40	X
Headlamp socket, RH	1	44.20	X
Wiper water tank	1	59.60	✓
Fender cowling @150.70	2	301.40	✓
Cowling clip	20	60.00	✓
Fender, front @387.90	2	775.80	✓
Engine under cover, front	1	117.30	
Clip		36.00	
Parts		11,031.45	
Parts less 25%		2,757.86	
		8,273.59	

To remove damaged parts and attachments
Cut n weld damaged panel
Repair/reshape dented/damaged areas
Straighten chassis where necessary
Replace/align all parts
To spray paint

1,100.00 *7000*

1,200.00 *1000*

10,573.59

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: