

HENG YAP SENG AUTO SERVICES

Blk 160, Sin Ming Drive, #08-13 Sin Ming AutoCity, Singapore 575722

Hp : 9183 3008

Fax : 6873 2017

Vehicle No : SKP6647E
Vehicle Model : Toyota Wish

Not Authorized
Repair B4 paint
82365.48

Estimate Repair Cost

No.	Qty	Parts List Items	
1	1	Rear bumper <i>491.90</i>	<i>Bul/nd</i> \$ 698.40 ✓
2	2	Rear bumper brackets	\$ R 130.60 X
3	2	Rear bumper retainers	<i>cls</i> \$ <i>nit</i> 132.20 <i>46.10</i>
4	2	Rear bumper reflectors	\$ <i>su</i> 132.20 X
5	1 set	Rear bumper clips	\$ <i>nu</i> 40.00 —
6	1	Rear fender RH	<i>nd</i> \$ <i>n</i> 806.20 <i>250sn</i>
7	1	Rear tailgate lamp RH <i>277.60</i>	<i>cm</i> \$ 303.10 —
8	1	Taillamp RH <i>411.70</i>	<i>cm</i> \$ 593.40 —
9	1	Tail lamp panel RH	\$ R 385.20 X
<i>258</i> Total			\$ 3,221.30

Labour

1	Labour charge to remove, cut out damage portion, jack out, straighten, panel beating, welding, align and renew replaced parts.	\$ 1,500.00 <i>480</i>
2	To putty and respray painting on affected areas.	\$ 1,200.00 <i>550</i>
3	To remove, replace rear fender fittings to facilitate repair.	\$ 300.00 <i>100</i>
4	To check wiring and lightings.	\$ 80.00 <i>20</i>

Total Labour \$ 3,080.00

Total Parts and Labour \$ 6,301.30

LKK Auto Consultants hence notify the Repairer of the following:

- To survey *C* before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: