

Date 09.06.20

Fax:

Vehicle Reg No. SHD3462P CTPL

05.06.20

Remarks:

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 05 Jun 2020)**Parts:** 143 HYUNDAI I40 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** ComfortDelGro Engineering Pte Ltd/SHD3462P/05/06/2020 18:26**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk ***Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER COVER	20.00	0.00	de ✓ *1,106.00 FL
2	10		*REAR BUMPER CLIPS	20.00	0.00	nh ✓ *22.00 FL
3	1		*REAR BUMPER UNDER COVER	20.00	0.00	RY ✓ *228.00 FL
4	1		*REAR BUMPER REVERSE SENSOR	0.00	0.00	nw ✓ *135.70 F
5	1		*REAR BUMPER RUBBER MAT	0.00	0.00	nh ✓ *50.00 F

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$) 1,541.70**- List Item Discount on L Items (\$\$)** 271.20**Total Parts (\$\$)** 1,270.50

ComfortDelGro Engineering Pte Ltd/SHD3462P/05/06/2020 18:26. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

1,128
- 20%
902.40
+ 185.70 Net
1,088.10

6/5/2020

Repairer Estimates

Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

1 1 OD/TP Case (Insurer)

11.00

Sub Total (\$\$)

11.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1 PANEL BEATING

2 SPRAY PAINTING CHARGE

3 REMOVE/REFIX REVERSE SENSOR

New

New

New

280.

200

30

350.00

250.00

80.00

Gross Labour Cost (\$\$)

680.00

ComfortDelGro Engineering Pte Ltd/SHD3462P/05/06/2020 18:26. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Tanjin 97495749
wp'

8/1/20 @ 345

02 days

Insurance \$1,300

Resum after repair
Tanjin @ 11 hours on.