

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Tokio Marine Insurance Singapore Ltd  
20 McCallum Street  
#09-01 Tokio Marine Centre  
Singapore 069046From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Telma Gomez

Date: 10 Jun 2020

**Preliminary Advice**

|                    |   |                         |              |
|--------------------|---|-------------------------|--------------|
| Insured Vehicle No | : SLU5900S  |                         |              |
| TP Vehicle No      | : SHD3462P  | Accident Date           | : 05/06/2020 |
| Make               | : HYUNDAI I40   | Assignment Date         | : 08/06/2020 |
| Date of Inspection | : 08/06/2020  | Est. Duration of Repair | : 2.00       |
| Inspection At      | : COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)<br>59 LOYANG DRIVE<br>SINGAPORE 508969 |                         |              |

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

|                             |      |          |
|-----------------------------|------|----------|
| Repairer's Estimate (Gross) | :S\$ | 1,961.50 |
| Revised Amount              | :S\$ | 1,609.10 |
| Check Items (Estimated)     | :S\$ | 0.00     |
| Total                       | :S\$ | 1,609.10 |
| <br>Lump Sum Repair         | :S\$ |          |

**Total Loss Consideration**

|                    |      |
|--------------------|------|
| New for Old Value  | :S\$ |
| Pre-Accident Value | :S\$ |
| COE / PARF Rebate  | :S\$ |
| Salvage Value      | :S\$ |
| Margin for Repair  | :S\$ |

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :