

NGS AUTOMOTIVE

Blk 10 Ang Mo Kio Ind. Pk 2a #02-01 AMK AutoPoint Singapore 568047
Tel: 64815727 Fax: 64815772 Email: evelyn1911ngsautomotive@gmail.com
Reg No.: 33405718K

QUOTATION

No. : AQT-0015

FWD SINGAPORE PTE LTD

6 TEMASEK BOULEVARD
#18-01 SUNTEC TOWER 4
SINGAPORE 038986

TEL : 6322 2072

FAX :

Your Ref. :
Our Ref : AQT-0015/SJS8238
C. C. :
Date : 11-06-2020
Page : 1 of 2

*Not Authorise
11 May 8?
Resurvey After Painting*

4-5 days

Description	Qty	U/ Price S\$	Amount S\$
ACCIDENT ON 10/06/2020@08:55 INVOLVING SJS8238K & SLA22655			
ALONG SLIP ROAD FROM SLE TOWARDS THOMSON ROAD			
CLAIMS AGAINST SLA22655 (FWD)			
REPLACEMENT PART: BMW528I			
REAR BUMPER	1	1,680.97	1,680.97 <i>Bj</i>
TRUNK LID	1	1,765.50	1,765.50 <i>Bj</i>
GUIDE, BOTTOM CENTER	1	58.85	58.85 <i>Sn</i>
GUIDE, CENTER REAR	1	71.69	71.69 <i>CM</i>
PROTECTION FOIL, RH/LH	2	11.00	22.00 <i>na</i>
SET OF MOUNTS, PDC SENSOR	1	62.06	62.06 <i>na</i>
TRIGGER CONTACT PDC SENSOR	1	X 144.45	144.45 <i>shag</i>
DECOUPLING PDC	4	5.50	22.00 <i>na</i>
COVER, TOW EYE	1	50.29	50.29 <i>Sn</i>
MOUNT, REAR RH/LH	2	198.40	396.80 <i>Sn</i>
BLIND RIVET NUT	3	3.50	10.50 <i>na</i>
EXPANDING RIVET	6	3.50	21.00 <i>na</i>
CARRIER, REAR BUMPER	1	829.25	829.25 <i>Bj</i>
ADAPTER, REAR BUMPER	1	116.63	116.63 <i>Bj</i>
RUBBER, TRUNK LID	1	70.62	70.62 <i>Sn</i>
TAILLAMP RH/LH	2	668.75	1,337.50 <i>MSG</i>
REAR LAMP, TRUNK LID RH/LH	2	394.83	789.66 <i>Sn</i>
GASKET, TAILLAMP	2	38.52	77.04 <i>na</i>
REFLECTOR, REAR BUMPER RH/LH	2	39.59	79.18 <i>Sn</i>
END PANEL	1	889.17	889.17 <i>na</i>
PARKING SENSOR	2/1	395.90	791.80 <i>shag</i>
REAR END GARNISH	1	136.00	136.00 <i>Sn</i>

NGS AUTOMOTIVE

Blk 10 Ang Mo Kio Ind. Pk 2a #02-01 AMK AutoPoint Singapore 568047
Tel: 64815727 Fax: 64815772 Email: evelyn1911ngsautomotive@gmail.com
Reg No.: 53405718K

QUOTATION

No. : AQT-0015

FWD SINGAPORE PTE LTD

6 TEMASEK BOULEVARD
#18-01 SUNTEC TOWER 4
SINGAPORE 038986

TEL : 6322 2072

FAX :

Your Ref. :

Our Ref : AQT-0015/SJS8238

C. C. :

Date : 11-06-2020

Page : 2 of 2

Description	Qty	U/ Price S\$	Amount S\$
SubTotal			9,422.96
LESS 5%			
EMBLEM '528'	1	471.15	471.15
S.NETT	1	68.50	68.50
BADGE	1	75.95	75.95
S.NETT	2	3.50	7.00
GROMMET	1	50.00	50.00
S.NETT	1	1,400.00	1,400.00
NO PLATE			550
TO REMOVE ALL DAMAGED PART WITH ALL NECESSARY COMPONENT/ATTACHMENT. STRAIGHTEN CHASSIS MEMBER, REPAIR/RESHAPE DENTED BODY PANEL. REPLACE DAMAGED PART. REFIT INTO POSITION.	1		660
TO SPRAY PAINTING	1	1,000.00	1,000.00
TO TRANSFER TRUNK LID MECHANISM	1	150.00	150.00
CHECK WIRING & LIGHT FUNCTION	1	100.00	100.00
RADAR			

Covering lower right \$40.15 CM ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Any other parts which necessitate repair or renewal will incur additional charges on a "Without Prejudice" basis. Please contact our Ms Evelyn @ HP 96955547 to arrange for survey. Thank you.

Total 11,803.26

Yours faithfully,



Administrator

Acknowledged by Repairer

Signature:

Date: