



# MY CAR CONSULTANT PTE LTD

Reg no.: 201605878Z

Address: 53 Ubi Ave 1 #01-33 Paya Ubi Industrial Park Singapore 408934

HP: 98888885

Steve (LKK) *WL RL* Estimation  
 10/6/20, 10:30 am  
 5 days, L/S  
 My AL My

Date: 9/6/2020  
 Vehicle: GBB9156R  
 Make / Model: TOYOTA HIACE  
 Chassis No: JTFHT02P30-0061001

No.	Description	Unit	Unit Price	Amount
Parts Replacement:				
1	LH REAR FENDER / <i>OD</i>	1	\$ 1,120.10	\$ 1,120.10
2	LH REAR TAILLAMP / <i>CVT</i>	1	\$ 277.20	\$ 277.20
3	LH REAR TAILLAMP LOWER APRON PANEL * <i>OR</i>	1	\$ 322.60	\$ 322.60
4	LH REAR TAILLAMP LOWER APRON PANEL CLIPS * <i>M 22</i>	1	\$ 5.89	\$ 11.78
5	REAR BUMPER / <i>CVT</i>	1	\$ 399.20	\$ 399.20
6	LH REAR BUMPER SIDE RETAINER / <i>TR</i>	1	\$ 46.70	\$ 46.70
7	LH REAR FENDER AIR VENT * <i>NM</i>	1	\$ 112.30	\$ 112.30
8	LH FRONT RIM * <i>NM</i>	1	\$ 256.80	\$ 256.80
				\$ 2,289.88
Less 25%				\$ 572.47
Total				\$ 1,717.41
S/Nett items:				
1	REAR BUMPER CLIP / <i>RPC</i>	1 SET	\$ 80.00	\$ 80.00
2	REAR END PANEL GARNISH CLIP * <i>NM</i>	1 SET	\$ 30.00	\$ 30.00
3	FLOOR PANEL SEALANT * <i>NM</i>	1	\$ 50.00	\$ 50.00
4	END PANEL SEALANT * <i>NM</i>	1	\$ 50.00	\$ 50.00
5	MISCELLANEOUS * <i>NM</i>	1	\$ 200.00	\$ 200.00
				\$ 410.00
Labour to:				
1	TO CHECK ELECTRICAL WIRING	1	\$ 80.00	\$ 80.00
2	TO RESPRAY UNDERCOATING	1	\$ 100.00	\$ 100.00
3	APPLY ANTI RUST ON AFFECTED AREAS	1	\$ 150.00	\$ 150.00
4	SPRAY PAINTING ON AFFECTED AREAS	1	\$ 600.00	\$ 600.00
5	PANEL BEATING ON AFFECTED AREAS	1	\$ 800.00	\$ 800.00
				\$ 1,730.00
Parts Replacement Amount			\$ 2,127.41	
Total Amount for Labour			\$ 1,730.00	
Total Amount			\$ 3,857.41	

158.70 ✓  
 2013.68  
 -25%  
 1510.26  
 30 ✓  
 30  
 30  
 350  
 600  
 1040

P- 1510.26  
 N- 30  
 L- 1040  
 2580.26  
 L/S- 2064.20  
 = 2050

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature: