

22/03/2002

ASS. REC. BY:

REF: CS3/SM019010466 / Gtf3-1

Special Instruction:

Surveyor: GA

ASSIGNMENT (Office)

From (Person) Henry, Irene James

of SMO

Date/Time: Tuesday, 9 June 2020 8:34 AM

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

SMF1571B - \$2400 - 4 days

To Inspect Vehicle No: SMF 1571B

Insured: SGZ 6819X

at Workshop m/s Toh Motor

Tel: 9748 3351

of 160 Sh Ming Drive #05-16

Policy No: D19MTPV01007431

Claim No: CM101902673

Sum Insured:

Excess:

Make of Veh:

D.O.A. 2.6.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 13.6.19 11.40 AM

Person Contacted: Ash

Vehicle IN/OUT

Date/Time	Action/Instruction ( X ) Estimate
	SMF 1571B - X
	SGZ 6819X - CC4/A1G/11021881 / ka293k2 D.O.A. - 21/10/2011
	Dismantle: 14/6/2019
	After repair: 19/6/2019

## ASSIGNMENT

From: \_\_\_\_\_ Date: 13-6-2019

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMF 1571Bat Workshop m/s Toh motorof 160 sin ming Drive #105-16

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_


Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SMF 1571B Yr Regn: 30 Oct 2018

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Prius c.c. 1798Colour: Black A/C: Insured / Std / NI / NASp. Reading: 45062 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: IT08 S36U70J034171

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / A/Rim or

Tyre Size: F: 205/60R16R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mmL/Bal. 6 mm

D.O.A. \_\_\_\_\_

Rear

R/Bal. 6 mmL/Bal. 6 mmD.O.I. 03-06-19Survey held at w/s

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

\$ 2000 - \$ 3000

17/6/2019

SMF1571B - \$2400 - 4 day  
(Red: 1900; 44%)

Date/Time, File Pass to?

☐ : Preli. Report  
☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: 3Resurvey No. of Trip: 2Add Fee: ☐ : Site Insp (\$ ) \$ + RS \$ SI☐ : Interview (\$ )☐ : Tech. Invs (\$ )☐ : Weekend (\$ )

Survey Fee:

Transportation:

Photos

Others

TOTAL

Report Format: PRS

Lump Sum / I.B.I: (\$ )

100

60

60

11

231