

ASS. REC. BY:

REF:

TII / 200062601kb

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

08 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

9/23

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLU 7498Z

Yr Regn: 09, 08

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mit Lancer

c.c 1584

Colour

M. Black

A/C: Insured / Std / NI / NA

Sp. Reading

240.572

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JMYSNCS3A8U 008054

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / STRim / STD A/Rim or

Tyre Size:

F:

195/60R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

1 tabilead

Front

Rear

R/Bal.

8

mm

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

10/6/20

D.O.I.

11/6/2020

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

30/6 21:20 @ 5750h Carline

Date/Time, File Pass to?

☐

Prell. Report

1)

Date/Time, File Return to?

☐

Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

TOTAL

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S : INDIA INT'L INSURANCE PTE LTD

64 CECIL STREET
 #04/#05 IOB BUILDING
 SINGAPORE 049711

TEL: 63476100

FAX: 62247743

ATTN: Motor Claim Department

WS Ref: TP/III

Claim Type: Third Party

Accident Date: 10/06/2020

TP Veh Reg No: SHC1324Z

Estimate No: ES2090454/WS

Date: 11 Jun 2020

Policy No: 5103582613-01DC

Veh Reg No: SLU7498Z

Make/Model: MIT MIT LANCER 1.6M

Chassis No: JMYSNCS3A8U006054

Engine No: 4G18JS4691

Reg. Date:

Not Authorized

1/1 Imp @ 25150

Presumy After Pains

8 days

Estimate Repair Cost to Vehicle No :SLU7498Z

Description	U/Price	Quantity	List Price	Amount
			SS	SS
Net Price				
1 REAR BUMPER	697.00	1 PC	B ₁ 697.00	✓
2 REAR BUMPER CENTRE BEAM	209.00	1 PC	B ₁ 209.00	✓
3 REAR BUMPER SIDE RETAINER	58.00	2 PC	D ₁ 116.00	✓
4 REAR BUMPER CLIP	3.50	6 PC	M ₁ 21.00	✓
5 REAR CENTRE PANEL	495.00	1 PC	B ₁ 495.00	✓
6 REAR CENTRE PANEL INNER TOP GARNISH	156.00	1 PC	D ₁ 156.00	✓
7 TAILLAMP	414.00	2 PC	C ₁ 828.00	✓
8 TAILLAMP INNER CLIP	5.50	2 PC	M ₁ 11.00	✓
9 REAR BOOT	697.00	1 PC	B ₁ 697.00	✓
10 REAR BOOT INNER LOCK	64.00	1 PC	M ₁ 64.00	✓
11 REAR BOOT INNER RUBBER	175.00	1 PC	D ₁ /D ₁ 175.00	508.00
12 REAR BOOT LH HINGE	84.00	1 PC	B ₁ 84.00	✓
13 REAR BOOT LOGO	55.00	1 PC	M ₁ 55.00	✓
14 REAR NUMBER PLATE GARNISH	100.00	1 PC	D ₁ 100.00	✓
15 REAR LH FENDER	841.00	1 PC	B ₁ 841.00	✓
16 REAR LH FENDER INNER SHIELD	69.00	1 PC	C ₁ 69.00	✓
17 REAR WINDSCREEN GLASS MOULDING	59.00	1 PC	M ₁ 59.00	✓
18 REAR LH MUD FLAP	60.00	1 PC	D ₁ 60.00	✓
19 REAR LH FENDER INNER GARNISH	212.00	1 PC	S ₁ 212.00	✓
			4,949.00	
Less 10%			494.90	4,454.10
Special Net				
20 REVERSE SENSOR	200.00	1 SET	C ₁ 200.00	✓
21 REAR SPARE TYRE PANEL TOP COAT	80.00	1 PC	M ₁ 80.00	60.00
22 REAR BOOT TOP SPOILER <i>(Car type)</i>	220.00	1 PC	M ₁ 220.00	✓
23 REAR WINDSCREEN GLASS SEALANT	40.00	1 PC	M ₁ 40.00	✓
			540.00	540.00
Labour				
24 REMOVE AND REFIX REAR WINDSCREEN GLASS	100.00	1 LA		✓
25 REMOVE & REFIX TOP ROOF LINING, SEAT, CARPET GARNISH	100.00	1 LA		✓
26 PANEL BEATING TO ACCIDENT AFFECTED AREAS	1,300.00	1 LA		1200.00

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : INDIA INT'L INSURANCE PTE LTD

64 CECIL STREET
#04/#05 IOB BUILDING
SINGAPORE 049711

TEL: 63476100

FAX: 62247743

ATTN: Motor Claim Department

WS Ref: TP/III

Claim Type: Third Party

Accident Date: 10/06/2020

TP Veh Reg No: SHC1324Z

Estimate No: ES2090454/WS

Date: 11 Jun 2020

Policy No: 5103582613-01DC

Veh Reg No: SLU7498Z

Make/Model: MIT MIT LANCER 1.6M

Chassis No: JMYSNCS3A8U006054

Engine No: 4G18JS4691

Reg. Date:

Estimate Repair Cost to Vehicle No :SLU7498Z

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
27 PUTTY & RESPRAY ON REAR SPARE TYRE COMPARTMENT,REAR BOTH FENDERS,REAR BOOT,SPOILER,REAR PANEL & REAR BUMPER	1,100.00	1 LA	1,100.00	1000
28 RUSTPROOFING	90.00	1 LA	90.00	✓
			2,690.00	2,690.00
			Total	S\$ 7,684.10
			Add GST @ 7%	537.89
			Total Amount Payable	S\$ 8,221.99

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE