

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S : INDIA INT'L INSURANCE PTE LTD

64 CECIL STREET
 #04/#05 IOB BUILDING
 SINGAPORE 049711

TEL: 63476100

FAX: 62247743

ATTN: Motor Claim Department

WS Ref: TP/III

Claim Type: Third Party

Accident Date: 10/06/2020

TP Veh Reg No: SHC1324Z

Estimate No: ES2090454/WS

Date: 11 Jun 2020

Policy No: 5103582613-01DC

Veh Reg No: SLU7498Z

Make/Model: MIT MIT LANCER 1.6M

Chassis No: JMYSNCS3A8U006054

Engine No: 4G18JS4691

Reg. Date:

Not Authorised

1/15mp & ?

Presumy After Pains

8 days

Estimate Repair Cost to Vehicle No :SLU7498Z

Description	U/Price	Quantity	List Price	Amount
			SS	SS
Net Price				
1 REAR BUMPER	697.00	1 PC	<i>B1</i> 697.00	<i>✓</i>
2 REAR BUMPER CENTRE BEAM	209.00	1 PC	<i>B1</i> 209.00	<i>✓</i>
3 REAR BUMPER SIDE RETAINER	58.00	2 PC	<i>D11</i> 116.00	<i>✓</i>
4 REAR BUMPER CLIP	3.50	6 PC	<i>na</i> 21.00	<i>✓</i>
5 REAR CENTRE PANEL	495.00	1 PC	<i>B1</i> 495.00	<i>✓</i>
6 REAR CENTRE PANEL INNER TOP GARNISH	156.00	1 PC	<i>na</i> 156.00	<i>✓</i>
7 TAILLAMP	414.00	2 PC	<i>CM</i> 828.00	<i>✓</i>
8 TAILLAMP INNER CLIP	5.50	2 PC	<i>na</i> 11.00	<i>✓</i>
9 REAR BOOT	697.00	1 PC	<i>B1</i> 697.00	<i>✓</i>
10 REAR BOOT INNER LOCK	64.00	1 PC	<i>na</i> 64.00	<i>✓</i>
11 REAR BOOT INNER RUBBER	175.00	1 PC	<i>na/d11</i> 175.00	<i>5081m</i>
12 REAR BOOT LH HINGE	84.00	1 PC	<i>B1</i> 84.00	<i>✓</i>
13 REAR BOOT LOGO	55.00	1 PC	<i>na</i> 55.00	<i>✓</i>
14 REAR NUMBER PLATE GARNISH	100.00	1 PC	<i>D11</i> 100.00	<i>✓</i>
15 REAR LH FENDER	841.00	1 PC	<i>Bu</i> 841.00	<i>✓</i>
16 REAR LH FENDER INNER SHIELD	69.00	1 PC	<i>CM</i> 69.00	<i>✓</i>
17 REAR WINDSCREEN GLASS MOULDING	59.00	1 PC	<i>na</i> 59.00	<i>✓</i>
18 REAR LH MUD FLAP	60.00	1 PC	<i>D11</i> 60.00	<i>✓</i>
19 REAR LH FENDER INNER GARNISH	212.00	1 PC	212.00	<i>?</i>
			4,949.00	
	Less 10%		494.90	4,454.10
Special Net				
20 REVERSE SENSOR	200.00	1 SET	<i>CM</i> 200.00	<i>✓</i>
21 REAR SPARE TYRE PANEL TOP COAT	80.00	1 PC	<i>na</i> 80.00	<i>605m</i>
22 REAR BOOT TOP SPOILER <i>(Car type)</i>	220.00	1 PC	<i>na</i> 220.00	<i>✓</i>
23 REAR WINDSCREEN GLASS SEALANT	40.00	1 PC	<i>na</i> 40.00	<i>✓</i>
			540.00	540.00
Labour				
24 REMOVE AND REFIX REAR WINDSCREEN GLASS	100.00	1 LA	100.00	<i>✓</i>
25 REMOVE & REFIX TOP ROOF LINING,SEAT,CARPET GARNISH	100.00	1 LA	100.00	<i>✓</i>
26 PANEL BEATING TO ACCIDENT AFFECTED AREAS	1,300.00	1 LA	1,300.00	<i>1200l</i>

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : INDIA INT'L INSURANCE PTE LTD
64 CECIL STREET
#04/#05 IOB BUILDING
SINGAPORE 049711

TEL: 63476100 FAX: 62247743
ATTN: Motor Claim Department
WS Ref: TP/III
Claim Type: Third Party
Accident Date: 10/06/2020
TP Veh Reg No: SHC1324Z

Estimate No: ES2090454/WS
Date: 11 Jun 2020
Policy No: 5103582613-01DC
Veh Reg No: SLU7498Z
Make/Model: MIT MIT LANCER 1.6M
Chassis No: JMYSNCS3A8U006054
Engine No: 4G18JS4691
Reg. Date:

Estimate Repair Cost to Vehicle No :SLU7498Z

Description	U/Price	Quantity	List Price	Amount
			S\$	S\$
27 PUTTY & RESPRAY ON REAR SPARE TYRE COMPARTMENT,REAR BOTH FENDERS,REAR BOOT,SPOILER,REAR PANEL & REAR BUMPER	1,100.00	1 LA	1,100.00	1000.00
28 RUSTPROOFING	90.00	1 LA	90.00	✓
			2,690.00	2,690.00
Total				S\$ 7,684.10
Add GST @ 7%				537.89
Total Amount Payable				S\$ 8,221.99

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE