

MG SOLUTION PTE LTD

8737
23x5

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

Email : mg3solution@gmail.com

TO	: FWD	DATE	: 11/06/2020
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: SMP1674K		
MODEL	: TOYOTA COROLLA ALTIS 1.6 A		<i>Cecilia.</i>
CHASSIS NO			
<u>ACCIDENT DETAILS</u>			
	DATE : 10-Jun-20		
	TIME : 13:40HRS		
THIRD PARTY REQUESTOR / CONTACT	: JACK LI		

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	BOOTLID <i>3M</i>	1	\$ 769.60	\$ 769.60
2	BOOTLID LOGO <i>3M</i>	1	\$ 70.00	\$ 70.00
3	BOOTLID EMBLEM '1.6'	1	\$ 44.00	\$ 44.00
4	BOOTLID EMBLEM 'LX'	1	\$ 36.00	\$ 36.00
5	BOOTLID EMBLEM 'COROLLA'	1	\$ 36.00	\$ 36.00
6	BOOTLID EMBLEM 'ALTIS" <i>new</i>	1	\$ 35.00	\$ 35.00
7	BOOTLID TOP LOCK <i>new</i>	1	\$ 79.00	\$ 79.00
8	BOOTLID WEATHERSTRIP	1	\$ 157.00	\$ 157.00
9	BOOTLID REFLECTOR RH	1	\$ 140.00	\$ 140.00
10	REAR BUMPER <i>Detached</i>	1	\$ 580.00	\$ 580.00
11	REAR BUMPER SIDE RETAINER <i>new</i>	2	\$ 58.00	\$ 116.00
12	REAR BUMPER REFLECTOR <i>new</i>	2	\$ 85.30	\$ 170.60
13	REAR END REINFORCEMENT BAR <i>new</i>	1	\$ 211.30	\$ 211.30
14	REAR END REINFORCEMENT SPONGE <i>could</i>	1	\$ 91.20	\$ 91.20
15	TAILLAMP <i>new</i>	2	\$ 375.00	\$ 750.00
16	REAR END PANEL <i>Peris</i>	1	\$ 708.00	\$ 708.00
17	REAR END PANEL TOP GARNISH <i>Detached</i>	1	\$ 126.00	\$ 126.00

TOTAL PRICE \$ 4,119.70

818.20
613.65

LESS 25% \$ 1,029.93

SUB TOTAL PRICE \$ 3,089.78

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE <i>New</i>	1	\$ 50.00	\$ 50.00
2	REAR BUMPER CLIPS(SET) <i>New</i>	1	\$ 20.00	\$ 20.00
3	TAILLAMP CLIPS(SET) <i>New</i>	1	\$ 20.00	\$ 20.00
4	REAR END PANEL TOP GARNISH CLIPS(SET) <i>new</i>	1	\$ 20.00	\$ 20.00
5	REAR END PANEL INSULATION SEAL <i>New</i>	1	\$ 150.00	\$ 150.00
6	REVERSE SENSOR <i>Denyed</i>	1	\$ 220.00	\$ 220.00
			TOTAL	\$ 480.00

290

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,000.00	<i>400</i>	
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,000.00	<i>400</i>	
3	TUFF COAT	\$ 350.00	<i>60</i>	
4	WIRING CHECK	\$ 150.00	<i>30</i>	
5	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	<i>50</i>	
6	TRANSFER BOOTLID MECHANISM	\$ 80.00	<i>X</i>	

940

TOTAL \$2,660.00

TOTAL PARTS COST : \$ 3,569.78

TOTAL LABOUR COST : \$ 2,660.00

TOTAL REPAIR COST : \$ 6,229.78

APPROVED DETAILS

EXCESS :
NO. OF WORKING DAYS :
RE-SURVEY :

PART BY PART OR LUMP SUM :

DATE & TIME OF SURVEY :
SURVEYED BY :
CONTACT NUMBER :
FAX NUMBER :

Adrian Lj
2/s 12/06/20
04 Days

label: 1843-65
4/s: 141K