

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Irene Tay Hui Ping

Date: 11 Jun 2020

**Preliminary Advice**

Vehicle No	: GBD8155P	Accident Date	: 29/01/2020
Make	: NISSAN CABSTAR	Policy No.	: DMCVSN1935561900
Assignment Date	: 10/06/2020	Excess	: S\$3,600.00
Date of Inspection	: 10/06/2020	Est. Duration of Repair	: -
Inspection At	: Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A Singapore 768761		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front o/s portion & n/s body and parts claimed are consistent to the accident. The undercarriage & body structure affected due to collision.

Repairer's Estimate (Gross)	:S\$	TOTAL LOSS
Revised Amount	:S\$	TOTAL LOSS
Check Items (Estimated)	:S\$	TOTAL LOSS
Total	:S\$	TOTAL LOSS

Lump Sum Repair	:S\$
-----------------	------

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	31,000.00
COE / PARF Rebate	:S\$	20,225.00
Salvage Value	:S\$	
Margin for Repair	:S\$	10,775.00

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( X ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : Vehicle recommended total loss.