

SERVICE ESTIMATE

85426 - C00001 SL: SERVICE SALES - PC

Ms Xie Tingting
64 Tanah Merah Kechil Avenue
#06-25

Singapore 465531

Closed by : Paul Ong Qing Yong
Svc Consultant :
Remarks : Ms Xie Tingting

GST Reg.No:M28920628X
Inv.No. . : B&P 0 Page 1
Inv.date. : 05/06/2020
WIP No. . : 21347
Veh.In/Out:
*Tel.No. . : Mobile: 81888063
Reg.No. . : SLC3770H
Reg.date . : 12/05/2016
Mileage ... : 0
Chassis No: SAJAC12M0GPV93525

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE RHF WING MIRROR SIGNAL LAMP, MIRROR COVER, ASSY, ETC	0	1800.00	0		1,800.00	S
800	TO SPRAYPAINT ON RHF WING MIRROR COVER	0	400.00	0		400.00	S
280	TO CHECK WIRING INLCUDE RESETTING OF ALL ELECTRICAL MODULES	0	525.00	0		525.00	S
	MIRROR-DOOR	1.0 EA	1213.30			1,213.30	S
	MIRROR COVER RH XF R	1.0 EA	175.40			175.40	S
	LAMP	1.0 EA	159.00			159.00	S

Gross Total. 4,272.70

Labour Total 2,725.00
Parts Total 1,547.70
Package Total 0.00

Net..... 4,272.70
GST @ 7.0% 299.09
Total..... 4,571.80
Paid..... 0.00
Please Pay.. 4,571.80

GST: S=StdRated; O=OutOfScope; Z=ZeroRated