

CS/MSG 20006270/Dsg 3

TOTAL

GOH LEE HWA AUTOMOBILE PTE LTD

Block 5033 Ang Mo Kio Industrial Park 2

#01-255 Singapore 569536

Tel No: (65) 6482 5168

Fax No. (65) 6482 4452

Co.reg no. 200808259H

Reference No: 12620**Date: 12.06.2020****Jayaraman Ramesh****18 Kasai Road****Singapore 808265****KIA Sorento 2.2A Diesel****Estimated Repair Cost for Vehicle Reg. No: SLF 9325 E****REPLACEMENT OF DAMAGED PANELS / PARTS**

1 Pc. Rear Boot	bt / Dented	1,799.00	✓
1 Pc. Rear Boot Lock	Dem	298.60	✓
1 Pc. Rear Boot Garnish	NH	428.00	X
1 Pc. Rear Boot KIA Emblem	NH	50.00	✓
2 Pcs. Rear Boot Lamp	NH @ 299.00	598.00	X
1 Pc. Rear Boot Weather Slip	NH	410.00	✓
2 Pcs. Rear Boot Absorber	NH @ 480.00	960.00	X
1 Pc. Rear Sorento Emblem	NH	48.00	✓
1 Pc. Rear ECO Dynamics Emblem	NH	40.00	✓
1 Pc. Rear C&C Logo	NH	30.00	✓
2 Pcs. Rear Lamp	NH @ 365.00	730.00	X
1 Pc. Rear Bumper Top	Crnt / distorted	746.00	✓
1 Pc. Rear Bumper Lower	Crnt	720.00	✓
1 Pc. Rear Bumper Skid Plate	Crnt	199.00	✓
1 Pc. Rear Bumper Towing Cover	distorted	59.00	✓
1 Pc. Rear Bumper Reinforcement	crack / broken	468.00	✓
1 Pc. Rear Bumper Under Cover	NH	98.30	X
6 Pcs. Rear Bumper Parking Sensor	Dem @ 305.00	610.00	✓
1 Pc. Rear Bumper Parking Wire	NH	410.00	X
2 Pcs. Rear Bumper Side Catch	ols crack N/S NH @ 199.00	398.00	✓
12 Pcs. Rear Bumper Clips	NH @ 5.80	69.60	✓
2 Pcs. Rear Bumper Reflector	ols mainly crack N/S NH @ 118.00	236.00	✓
1 Pc. Rear End Panel	Dented N/S NH	795.00	✓
1 Pc. Rear End Panel Garnish	mainly broken	389.00	✓
1 Pc. Rear Spare Tyre Board	NH	389.00	X
1 Pc. Rear Spare Tyre Sponge	NH	290.80	X

GOH LEE HWA AUTOMOBILE PTE LTD

Block 5033 Ang Mo Kio Industrial Park 2

#01-255 Singapore 569536

Tel No: (65) 6482 5168

Fax No. (65) 6482 4452

Co.reg no. 200808259H

1 Pc. Rear Exhaust <i>st / distributor</i>		1,760.00	✓
2 Pcs. Rear Exhaust Mounting <i>HL</i>	@ 60.00	120.00	X
1 Pc. Rear Windscreen Seal <i>HL</i>		120.00	✓
1 Pc. Rear Windscreen Repair Kit <i>HL</i>		180.00	✓
Total (Panels / Parts):		<u>13,449.30 (SGD)</u>	

LABOR CHARGES

To check wiring & remove, refit wire.	180.00 <i>30/-</i>
To remove & refit interior garnish side board & all affected area.	250.00 <i>120/-</i>
To remove & refit windscreen.	180.00 <i>120/-</i>
To remove & refit exhaust.	180.00 <i>60/-</i>
To knocking, straightening repair & renew all accident affected area.	1,200.00 <i>700/-</i>
To respray painting on all accident affected area.	1,300.00 <i>700/-</i>
To rust proof all accident affected area.	120.00 <i>40/-</i>
To wash interior & vacuum.	280.00 <i>80/-</i>
Total (Labor Charges):	<u>3,690.00 (SGD)</u>

GOH LEE HWA AUTOMOBILE PTE LTD

Block 5033 Ang Mo Kio Industrial Park 2

#01-255 Singapore 569536

Tel No: (65) 6482 5168

Fax No. (65) 6482 4452

Co.reg no. 200808259H

TOTAL COST SUMMARY

PANELS / PARTS	13,449.30
LABOR CHARGES	3,690.00

Grand Total:	<u>17,139.30 (SGD)</u>
---------------------	-------------------------------

We shall be glad if you can forward the payment at your early convenience.

Cheque should be crossed and make payable to 'GOH LEE HWA AUTOMOBILE PTE LTD'

Alfred Quah

GOH LEE HWA AUTOMOBILE PTE LTD [WITHOUT PREJUDICE SAVE AS TO COSTS]

15/06/2020 @ 1700hrs

*Not Answered
2/3rd of 6 days.*

T. Yau

LKK Auto

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Check Part prices.