

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 10-Jun-20

INSURANCE: First Capital

MODEL: HYUNDAI I40

VEHICLE NO.: SHC1996J

DESCRIPTION	QTY	LIST PRICE	AMOUNT
BONNET <i>1st</i>	1	\$2,265.90	\$2,265.90
BONNET RUBBER (LH) <i>NH</i>	1	\$35.70	\$35.70
BONNET HINGE (LH) <i>NH</i>	1	\$126.70	\$126.70
BONNET INSULATOR <i>NH</i>	1	\$202.50	\$202.50
BONNET SEAL <i>NH</i>	1	\$31.90	\$31.90
BONNET INSULATOR CLIPS <i>NH</i>	1	\$15.00	\$15.00
RADIATOR GRILLE H EMBLEM <i>NH</i>	1	\$129.50	\$129.50
RADIATOR GRILLE <i>broken Not consistent.</i>	1	\$1,480.00	\$1,480.00
FRONT BUMPER COVER <i>dent</i>	1	\$1,052.20	\$1,052.20
FRONT BUMPER SPONGE <i>NH</i>	1	\$379.20	\$379.20
FRONT BUMPER REINFORCEMENT <i>NH</i>	1	\$588.40	\$588.40
FRONT BUMPER GRILLE (LH) <i>NH</i>	1	\$149.20	\$149.20
FRONT BUMPER BRACKET TOP (LH) <i>NH</i>	1	\$44.80	\$44.80
FRONT BUMPER BRACKET (LH) <i>broken</i>	1	\$49.20	\$49.20
FRONT BUMPER RETAINER MOUNTING <i>NH</i>	1	\$76.20	\$76.20
FRONT BUMPER GRILLE AIR DUCT (LH) <i>NH</i>	1	\$126.20	\$126.20
HEADLAMP SUPPORT PANEL ASSY <i>1st / correct photo</i>	1	\$907.40	\$907.40
HEADLAMP (LH) <i>broken 1198-50</i>	1	\$2,776.00	\$2,776.00
HEADLAMP SUPPORT TOP COVER <i>NH</i>	1	\$222.60	\$222.60
RADIATOR <i>NH</i>	1	\$1,637.20	\$1,637.20
RADIATOR GUARD (LH) <i>NH</i>	1	\$76.50	\$76.50
FRONT FENDER (LH) <i>enc</i>	1	\$566.30	\$566.30
FRONT FENDER APRON PANEL (LH) <i>dent photo</i>	1	\$637.00	\$637.00
FRONT FENDER SHIELD (LH) <i>NH</i>	1	\$174.90	\$174.90
AIRCON CONDENSER <i>NH</i>	1	\$947.80	\$947.80
FRONT WHEEL RIM (LH) <i>NH</i>	1	\$650.60	\$650.60
KNUCKLE ARM (LH) <i>distorted</i>	1	\$595.90	\$595.90
FRONT WHEEL BEARING HUB ASSY (LH) <i>distorted</i>	1	\$673.20	\$673.20
FRONT SUSPENSION LOWER ARM (LH) <i>distorted</i>	1	\$1,104.00	\$1,104.00
FRONT SHOCK ABSORBER ASSY (LH) <i>distorted</i>	1	\$684.40	\$684.40
FRONT SHOCK ABSORBER MOUNTING (LH) <i>NH</i>	1	\$217.60	\$217.60
STG TIE ROD (LH) <i>NH</i>	1	\$186.40	\$186.40
STG TIE END (LH) <i>NH</i>	1	\$125.20	\$125.20
STABILIZER BAR ASSY <i>NH</i>	1	\$463.70	\$463.70
STABILIZER BAR LINK (LH) <i>NH</i>	1	\$68.10	\$68.10
ABS SENSOR <i>NH</i>	1	\$217.90	\$217.90
INTER COOLER <i>NH</i>	1	\$1,032.50	\$1,032.50
HOSE B TO INTER COOLER <i>NH</i>	1	\$229.70	\$229.70
HOSE C TO INTER COOLER INLET <i>NH</i>	1	\$294.50	\$294.50
SUB TOTAL			\$21,242.00
LESS 20%			\$4,248.40
DISCOUNTED TOTAL			\$16,993.60

COOLANT NH	SN	1	\$ 45.00	\$ 45.00	X
FRONT TYRE (LH) NH	SN	1	\$216.00	\$216.00	X
SUB TOTAL				\$261.00	
Labour Charge					
Panel Beating		1	\$1,400.00	\$1,400.00	7600/-
Spray Painting Charge		1	\$1,200.00	\$1,200.00	700/-
Wiring Charge		1	\$100.00	\$100.00	30/-
Tuff Kote		1	\$100.00	\$100.00	40/-
Towing Charge		1	\$80.00	\$80.00	77
Four Wheel Alignment		1	\$120.00	\$120.00	760/-
Remove/Refix Undercarriage (Frt)		1	\$400.00	\$400.00	77150/-
Re-set Frt ABS System		1	\$200.00	\$200.00	77
Remove/Refix Radiator		1	\$90.00	\$90.00	77
Remove/Refix Aircon & Refill Gas		1	\$130.00	\$130.00	77
Remove/Refix Fuse Box		1	\$120.00	\$120.00	77
Remove/Refix Engine		1	\$600.00	\$600.00	77
TOTAL LABOUR				\$4,540.00	
ESTIMATE TOTAL				\$ 21,794.60	
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					

11/06/2020 @ 1715hrs

Not Author

2/Sumel 5 days.

Yan

2kk Auto

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: