

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC6/AIG20006279/KDS3Q2

**Date:** 13/08/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100462194

**Claimant**  
**Vehicle No :** SGX7Y **Insured Vehicle No :** GBE8994D

Date of Loss: 07/06/2020 Nature of Claim: TP Claim No: 5215694759SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |  |             |                   |
|-----------------------------|--|-------------|-------------------|
| Reg No:                     | <b>SGX7Y</b>   |             |                   |
| Make & Model:               | MERCEDES-BENZ E200, 2.0 AVG A/T ABS<br>AIRBAGS 2WD (A) | Engine No:  | 27492030812912    |
| Reg. Date:                  | 13/02/2017 (Man. Year: 2016)                           | Chassis No: | WDD2130422A102884 |
| Colour:                     | Metallic Grey  | Odometer:   | 130519 km         |
| Engine Capacity:            | 1991 cc  |             |                   |
| Market Value/New Car Price: | N/A  |             |                   |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b>                      |             |                   |

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

### CONDITION OF TYRES

|                   |              |                  |              |
|-------------------|--------------|------------------|--------------|
| Front Tyre Size:  | 225/55 R17   | Rear Tyre Size:  | 225/55 R17   |
| Front Left Side:  | Pirelli 8 mm | Rear Left Side:  | Pirelli 8 mm |
| Front Right Side: | Pirelli 8 mm | Rear Right Side: | Pirelli 8 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                                       | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|---|-------------------|-------------------|-------------------|---------------|
| Parts   | 7,289.73          | 4,762.17          | 2,527.56          | 34.67         |
| Miscellaneous Items   | 0.00              | 0.00              | 0.00              |               |
| Labour  | 2,060.00          | 1,380.00          | 680.00            | 33.01         |
| Paintwork Labour  | 0.00              | 0.00              | 0.00              |               |
| Towing  | 0.00              | 0.00              | 0.00              |               |
| <b>Gross Total (S\$)</b>                                    | <b>9,349.73</b>   | <b>6,142.17</b>   | <b>3,207.56</b>   | <b>34.31</b>  |
| <b>+ GST 7.00/7.00% (S\$)</b>                               | 654.48            | 429.95            | 224.53            | 34.31         |
| <b>Nett Amount (S\$)</b>                                    | <b>10,004.21</b>  | <b>6,572.12</b>   | <b>3,432.09</b>   | <b>34.31</b>  |
| <b>+ Car Rental (4.0 x S\$120.00/day + 7.00% GST) (S\$)</b> |                   | 513.60            |                   |               |
| <b>+ Doc/Search Fee (S\$)</b>                               |                   | 2.00              |                   |               |
| <b>Nett Liability (S\$)</b>                                 |                   | <b>7,087.72</b>   |                   |               |

### INSPECTION

Date of Assignment: 15/06/2020

Date Inspected: 15/06/2020 Inspected At: Optima Werkz Pte Ltd (HQ)  
6 Kung Chong Road  
Singapore 159143

Estimated Period of Repair: 4.0 days

**Adjuster:** KENNETH KONG

**Manager:** CHAN JIA LE

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

| No. | Qty | Part No. | Particulars                                  | Condition        | Repairer's  | Amount       |
|-----|-----|----------|--|------------------|-------------|--------------|
| 1   | 1   |          | *REAR BOOT LID                               | Bent             | 2,550.00 FL | *2,240.00 FL |
| 2   | 1   |          | *REAR BOOT LID EMBLEM                        | Necessary        | 78.00 FL    | *78.00 FL    |
| 3   | 1   |          | *REAR BOOT LID E 200 EMBLEM                  | Necessary        | 112.00 FL   | *112.00 FL   |
| 4   | 1   |          | *REAR BUMPER                                 | Buckled / Dented | 2,422.00 FL | *1,956.00 FL |
| 5   | 8   |          | *REAR BUMPER CLIPS                           | Necessary        | 49.60 FL    | *49.60 FL    |
| 6   | 1   |          | *REAR BUMPER LOWER LIP COVER                 | Serviceable      | 545.00 FL   | *- FL        |
| 7   | 1   |          | *REAR BUMPER LOWER LIP COVER CHROME MOULDING | Serviceable      | 362.00 FL   | *- FL        |
| 8   | 1   |          | *REAR TAIL LAMP LH                           | Scratched        | 855.70 FL   | *855.70 FL   |
| 9   | 1   |          | *REAR BUMPER INNER CENTER GUIDE              | Serviceable      | 196.40 FL   | *- FL        |
| 10  | 1   |          | *REAR BUMPER REINFORCEMENT                   | Repair           | 929.00 FL   | *- FL        |
| 11  | 1   |          | *REAR END PANEL (NPA)                        | Repair           | 0.00 FL     | *- FL        |

F=Franchise part. L=ListItemDisc.

|  |                 |                 |
|--|-----------------|-----------------|
| <b>Sub Total (\$\$)</b>                                    | <b>8,099.70</b> | <b>5,291.30</b> |
| <b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b> | 809.97          | 529.13          |

|                           |                 |                 |
|---------------------------|-----------------|-----------------|
| <b>Total Parts (\$\$)</b> | <b>7,289.73</b> | <b>4,762.17</b> |
|---------------------------|-----------------|-----------------|

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                             | Particulars  | Lab.Type | Repairer's      | Amount          |
|--------------------------------|--|----------|-----------------|-----------------|
| <b><u>Labour Items</u></b>     |  |          |                 |                 |
| 1                              | LABOUR CHARGES TO REMOVE,REPAIR ,REFIX ,REPLACE & READJUST REAR ACCIDENT AREAS & ETC                                     | New      | 800.00          | 600.00          |
| 2                              | LABOUR CHARGES TO REMOVE & REFIX REAR BUMPER REVERSE SENSOR & ETC .TO EFFECT REPLACE OF REAR BUMPER & ETC                | New      | 100.00          | 60.00           |
| 3                              | LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR BUMPER ,REAR BOOT LID ,REAR END PANEL & ETC | New      | 900.00          | 700.00          |
| 4                              | TO CHECK WIRING & ELECTRICAL SYSTEM & ETC  | New      | 80.00           | 20.00           |
| 5                              | TO DIAGNOSIS FAULT CODE & RESET MEMORY   | New      | 180.00          | 0.00            |
| <b>Gross Labour Cost (S\$)</b> |  |          | <b>2,060.00</b> | <b>1,380.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >