

Date: 08.06.2020
Vehicle No: SGX7Y
Model: MERCEDES BENZ E200
Chassis: WDD2130422A102884-2016
Reg.Year: 2017

Third Party Insurer: AIG
Third Party Veh No: GBE8994D
Date of Accident: 07.06.2020

*Not Authorized
Primary BQ print
(4 days)*

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR BOOT LID	1		\$2,550.00
2	REAR BOOT LID EMBLEM	1		\$78.00
3	REAR BOOT LID "E 200" EMBLEM	1		\$112.00
4	REAR BUMPER	1		\$2,422.00
5	REAR BUMPER CLIPS	8	\$6.20	\$49.60
6	REAR BUMPER LOWER LIP COVER	1		\$545.00
7	REAR BUMPER LOWER LIP COVER CHROME MOULDING	1		\$362.00
8	REAR TAIL LAMP LH	1		\$855.70
9	REAR BUMPER INNER CENTER GUIDE	1		\$196.40
10	REAR BUMPER REINFORCEMENT	1		\$929.00
11	REAR END PANEL	1		REPAIR
SUB TOTAL				\$8,099.70
LESS 10%				-\$809.97
PARTS TOTAL				\$7,289.73

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPAIR, REFIX, REPLACE & READJUST REAR ACCIDENT AREAS & ETC.

500
\$800.00

LABOUR CHARGES TO REMOVE & REFIX REAR BUMPER REVERSE SENSOR & ETC. TO EFFECT REPLACE OF REAR BUMPER & ETC.

100
\$100.00

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR BUMPER, REAR BOOT LID, REAR END PANEL & ETC.

500
\$900.00

TO CHECK WIRING & ELECTRICAL SYSTEM & ETC.

80
\$80.00

TO DIAGNOSIS FAULTY CODE & RESET MEMORY

180
\$180.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts price to be supplied on quotation

LABOUR TOTAL \$2,060.00

TingAn

Final repair cost to be provided on basis of final inspection and approval

TOTAL \$9,349.73

Supplementary items must be approved and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

branch

Branch

Head office

6 Kang Ching Road Singapore 159143
Tel: (+65) 6472 1213 | Fax: (+65) 6472 2112

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1011

551 Upper Thomson Road Singapore 574415
Tel: (+65) 6452 6868 | Fax: (+65) 6452 9223

