

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

PC7958K
TP/AIG

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

Estimate No: ES2090466/WS

Date: 17 Jun 2020

Policy No:

Veh Reg No: PC7958K

Make/Model: TOYOTA TOYOTA
HIACE COMMUTER
2.8GL

Chassis No: GDH2232001427

Engine No:

Reg. Date: 05/04/2019

WS Ref: TP AIG

Claim Type: Third Party

Accident Date: 29/05/2020

TP Veh Reg No: SJA3202R

Not Authorized

Recovery B4 paint
\$1212.58
4 days

Estimate Repair Cost to Vehicle No :PC7958K

Description	U/Price	Quantity	List Price S\$	Amount S\$
List Price				
1 REAR BUMPER	357.40	1 PC	357.40	
2 REAR BUMPER CLIP	3.50	6 PCS	21.00	
3 REAR BUMPER SIDE RETAINER RH	39.80	1 PC	39.80	
4 TAILLAMP RH	289.10	1 PC	289.10	
			707.30	
		Less 25%	176.83	530.48
Labour				
5 TO REMOVE AND REFIX REAR BUMPER, TAILLAMP, KNOCK AND REPAIR REAR RH SIDE PANLE AND RE-ALIGN TO SAME	500.00	1 LA	500.00	400
6 TO REMOVE AND REFIX REAR SEAT, CARPAT, GARNISH ETC	120.00	1 LA	120.00	80
7 TO PUTTY AND RESPRYA ON REAR RH SIDE PANEL, TAILLAMP LOWER GARNISH, REAR BUMPER	600.00	1 LA	600.00	500
			1,220.00	1,220.00
			Total	S\$ 1,750.48
			Add GST @ 7%	122.53
			Total Amount Payable	S\$ 1,873.01

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE