





SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 15/07/2020

User ID : CatherineLee

Section A - Accident Details	
Registration Number	SMB37E
Case Reference Number	BUS/06/20/5005
Registration Date	28/11/2008
Company Type	SMRT Buses Ltd
Make	MERCEDES
Model	MBOC500
Name of Driver	You Say Kau
Type of Accident	Side Swipe
Accident Date and Time	3/6/2020 10:00 AM
Accident Reported Date and Time	3/6/2020 11:45 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24107155
Special Instruction to ARC,if any	SMB37E-LEFT SIDE MIRROR CRACKED GBH4451P (TP) INSURED WITH AIG
Prepared Date and Time	8/6/2020 2:23 PM
Chassis Number	WEB63442021000098
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$530.00	\$265.00
Total Spray Cost	\$0.00	\$0.00
Total Spare Part Cost	\$900.00	\$900.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$1,430.00	\$1,165.00
Lump Sum Total	\$0.00	\$1,150.00
Number of Repair Days	1.0	0.5
Prepared / Adjusted By	Jeong Choon Hwee	Sun Pin (LKK)
ARC / Surveyor Sign Off Date	08/06/2020 4:05 PM	08/06/2020 4:38 PM
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 15/07/2020

User ID : CatherineLee

Section D - Details of Repair Estimates									
Part 1 - Labour Works									
Job Scope			Quotation from AR				Adjusted by Surveyor, if applicable		
TO REMOVE & INSTALL FRONT VIEW MIRROR LH			\$530.00				\$265.00 ✓		
Total Labour			\$530.00				\$265.00		
Part 2 - Spray Painting & Panel Beating Related Works									
Job Scope			Quotation from ARC				Adjusted by Surveyor, if applicable		
Total Spray Painting & Panel Beating									
Part 3 - Other Costs - Accident and Accident Repair Related Expense									
Job Scope			Quotation from ARC				Adjusted by Surveyor, if applicable		
Total Other Costs									
Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6012672			MIRROR,VIEW:REAR,ELECTRICAL,LH,MBOC500	1.00	\$1,250.00	10.00	\$1,125.00	Replace	Replace ✓ CRA
Total					\$1,250.00		\$1,125.00		
Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

1,125
- 20%

900
+ 265

1,165

HS
\$ 1,150
0.5 days