



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 08/06/2020

User ID : JeongCH

Section A - Accident Details		
Registration Number	SMB37E	
Case Reference Number	BUS/06/20/5005	
Registration Date	11/28/2008	
Company Type	SMRT Buses Ltd	
Make	MERCEDES	
Model	MBOC500	
Name of Driver	You Say Kau	
Type of Accident	Side Swipe	
Accident Date and Time	6/3/2020 10:00 AM	
Accident Reported Date and Time	6/3/2020 11:45 AM	
Is Surveyor Required?	Yes	
Survey by		
Vehicle is Towed Back?	No	
Towed Back Date and Time		
Replacement Vehicle issued?	No	
Job Card Number	24107155	
Special Instruction to ARC, if any	SMB37E-LEFT SIDE MIRROR CRACKED GBH4451P (TP) INSURED WITH AIG	
Prepared Date and Time	6/8/2020 2:23 PM	
Chassis Number	WEB63442021000098	
Mileage		
Work Shop		
Repair Completion Date and Time		

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$530.00	\$0.00
Total Spray Cost	\$0.00	\$0.00
Total Spare Part Cost	\$1,000.00	\$1,250.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$1,530.00	\$1,250.00
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	1.0	0.5
Prepared / Adjusted By	Jeong Choon Hwee	Sun Pin (LKK)
ARC / Surveyor Sign Off Date	08/06/2020 4:05 PM	08/06/2020 4:38 PM
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 08/06/2020

User ID : JeongCH

Section D - Details of Repair Estimates									
Part 1 - Labour Works									
Job Scope		Quotation from AR				Adjusted by Surveyor, if applicable			
TO REMOVE & INSTALL FRONT VIEW MIRROR LH		\$530.00				\$265.00			
Total Labour		\$530.00				\$265.00			
Part 2 - Spray Painting & Panel Beating Related Works									
Job Scope		Quotation from ARC				Adjusted by Surveyor, if applicable			
Total Spray Painting & Panel Beating									
Part 3 - Other Costs - Accident and Accident Repair Related Expense									
Job Scope		Quotation from ARC				Adjusted by Surveyor, if applicable			
Total Other Costs									
Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6012672			MIRROR,VIEW:REAR,EL ECTRICAL,LH,MBOC500	1.00	\$1,250.00	0.00	\$1,250.00	Replace	Replace / CRA
Total					\$1,250.00		\$1,250.00		
Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

Repair day - 0.5 days (half day)

Sun Pin CLKk)
08/06/2020
TP without prejudice.
L/S
After paint photo.

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company
Acknowledged by Repairer
Signature:
Date: