Shirley Hiew (LKK Auto)

From: Sent:	Boo seng yak <boojohnny@gmail.com> Monday, 15 June 2020 5:57 pm</boojohnny@gmail.com>
То:	Shirley Hiew (LKK Auto)
Cc:	Claims; Admin-D (LKKAuto); SUR; nora.khai@premiumauto.com.sg
Subject:	Re: OD CLAIM FOR SMA 9045 C ON 5/6/2020
Hi Chirloy and all	
Hi Shirley and all,	
Labour No : 1 can be remove	ed if rear bumper is not resprayed.
	oray charges, I suggest you refer to Adrian as there is no position at this moment for AIG to after surveyors recommendation.
Please ask Adrian to re-cacul	ate the painting charges and if there is any mistakes, we will undertake to rectify.
Please keep me inform of an	y changes.
Thank you n best regards - jb	
On Mon, Jun 15, 2020 at 2:1	6 PM Shirley Hiew (LKK Auto) < ShirleyHiew@lkkauto.com > wrote:
Dear Terrence,	
As instructed by our client	please proceed to repair the insured vehicle SMA 9045C (Excess S\$ 600.00/-).
715 mstructed by our enem,	please proceed to repair the insured vehicle givin 50450 (Excess 54 000.00/-).
If there are any check items arrange our surveyor for ins	or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to
urrange our surveyor for mo	poddon
All supplementary items and completion of the repair.	d unconfirm items are subjected to further approval from insurance company before
***************************************	hts mat to man if them is no well-dominated before manying
Our chefit reserve their rig	hts not to pay if there is no valid approval obtained before repair.
Note: Labour 1 to take out r	not necessary. Spray paint at 5 panels + door handle \$2850.00.
	· - · · - · · - · · · · · · · · · · · ·