

Hitachi Capital Asia Pacific Pte. Ltd.
Jun Taiyo Service Centre

No. 8 Fourth Lok Yang Road Singapore 629705
 Tel : 64663022 Fax : 68966591
 Co. Reg.No. 199400399N GST Reg.No. M2-011899-3

VEHICLE ESTIMATE dated 10/06/2020

LONPAC

ACCIDENT DATE : 09/06/2020 @ 13:35

ATTN: MOTOR CLAIMS DEPT

VRN : SKD8870B

MODEL : TOYOTA ALTIS 1.6

TP VRN : GBC9220H

	<u>Qty</u>	<u>S\$ Unit</u>	<u>S\$ Amt</u>	<u>S\$ Labor</u>
<u>PARTS REPLACEMENT</u>				
<u>1. Body Repair</u>				
1 FRONT BUMPER <i>de</i>	1	\$ 486.00	\$ 486.00	
2 FRONT BUMPER CLIP <i>acc</i>	10	\$ 5.50	\$ 55.00	
3 FRONT BUMPER RETAINER RH <i>cm</i>	1	\$ 58.00	\$ 58.00	
4 CENTER GRILLE <i>X SVC</i>	1	\$ 343.00	\$ 343.00 X	
5 HEADLAMP RH <i>bro</i>	1	\$ 650.00	\$ 650.00	
6 FRONT FENDER RH <i>bt</i>	1	\$ 610.00	\$ 610.00	
7 FRONT FENDER SHIELD RH <i>Torex</i>	1	\$ 237.00	\$ 237.00	
8 FRONT FENDER SHIELD CLIP <i>acc</i>	10	\$ 5.50	\$ 55.00	
9 SUPPORT PANEL <i>repair</i>	1	\$ 721.00	\$ 721.00 XR	
			\$ 3,215.00	
Discount -25%			\$ 803.75	
			\$ 2,411.25	
		PARTS TOTAL	\$ 2,411.25	

2. Labour Charges

Panel Beat, Cut, Weld, Re-align & Replace Damaged Parts Of FRONT Affected Area	500	\$ 1,250.00
Putty, Blend And Spray Paint on FRONT Affected Area	600	\$ 1,000.00
Check Wiring, Re-align Headlamps and Ensure Proper Functioning	40	\$ 80.00

LABOURS TOTAL \$ 2,330.00

Grand Total : \$ 4,741.25

Add 7% GST : \$ 331.89

Nett Total : \$ 5,073.14

No. of repair days: 7

Resue
4p 90010068
5 days
4p
10/06/2020 @ 1455
Resurvey after
repair

CUSTOMER SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____



HITACHI CAPITAL ASIA PACIFIC PTE LTD
 (MANAGER)

**Hitachi Capital Asia Pacific Pte. Ltd.
Jun Taiyo Service Centre**

No. 8 Fourth Lok Yang Road Singapore 629705
Tel : 64663022 Fax : 68966591
Co. Reg.No. 199400399N GST Reg.No. M2-011899-3

SUPPLEMENTARY VEHICLE ESTIMATE dated 26/06/2020

LONPAC

ATTN: MOTOR CLAIMS DEPT

ACCIDENT DATE : 09/06/2020 @ 13:35
VRN : SKD8870B
MODEL : TOYOTA ALTIS 1.6
TP VRN : GBC9220H

<u>Qty</u>	<u>S\$ Unit</u>	<u>S\$ Amt</u>	<u>S\$ Labor</u>
------------	-----------------	----------------	------------------

2. Labour Charges

Check, re-adjust and computerise wheel alignment / side slip test.

80 \$ ~~180.00~~

LABOURS TOTAL

\$ 180.00

80

1613.25
1140.00
80.00

2833.25
20%
2266.60

Grand Total : \$ 180.00
Add 7% GST : \$ 12.60
Nett Total : \$ 192.60

No. of repair days: 7

48-2,250
5 days



CUSTOMER SIGNATURE

HITACHI CAPTIAL ASIA PACIFIC PTE LTD
(MANAGER)