

Hitachi Capital Asia Pacific Pte. Ltd.
Jun Taiyo Service Centre

No. 8 Fourth Lok Yang Road Singapore 629705
 Tel : 64663022 Fax : 68966591
 Co. Reg.No. 199400399N GST Reg.No. M2-011899-3

VEHICLE ESTIMATE dated 10/06/2020

LONPAC

ATTN: MOTOR CLAIMS DEPT

ACCIDENT DATE : 09/06/2020 @ 13:35
 VRN : SKD8870B
 MODEL : TOYOTA ALTIS 1.6
 TP VRN : GBC9220H

	<u>Qty</u>	<u>S\$ Unit</u>	<u>S\$ Amt</u>	<u>S\$ Labor</u>
<u>PARTS REPLACEMENT</u>				
<u>1. Body Repair</u>				
1 FRONT BUMPER <i>de/</i>	1	\$ 486.00	\$ 486.00	
2 FRONT BUMPER CLIP <i>acc/</i>	10	\$ 5.50	\$ 55.00	
3 FRONT BUMPER RETAINER RH <i>cm/</i>	1	\$ 58.00	\$ 58.00	
4 CENTER GRILLE <i>X</i>	1	\$ 343.00	\$ 343.00	
5 HEADLAMP RH <i>bro/</i>	1	\$ 650.00	\$ 650.00	
6 FRONT FENDER RH <i>bl/</i>	1	\$ 610.00	\$ 610.00	
7 FRONT FENDER SHIELD RH <i>Torn/</i>	1	\$ 237.00	\$ 237.00	
8 FRONT FENDER SHIELD CLIP <i>acc/</i>	10	\$ 5.50	\$ 55.00	
9 SUPPORT PANEL <i>repair</i>	1	\$ 721.00	\$ 721.00	
			\$ 3,215.00	
Discount -25%			\$ 803.75	
			\$ 2,411.25	
PARTS TOTAL			\$ 2,411.25	

2. Labour Charges

Panel Beat, Cut, Weld, Re-align & Replace Damaged Parts Of FRONT Affected Area
 Putty, Blend And Spray Paint on FRONT Affected Area
 Check Wiring, Re-align Headlamps and Ensure Proper Functioning

500
 \$ 1,280.00
600
 \$ 1,000.00
 \$ 80.00

Passer
4p 90000068

LABOURS TOTAL \$ 2,330.00

No. of repair days: 7

5 days

43
10/06/2020 @ 1435

Resurvey after repair

Grand Total : \$ 4,741.25
Add 7% GST : \$ 331.89
Nett Total : \$ 5,073.14

CUSTOMER SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____

HITACHI CAPITAL ASIA PACIFIC PTE LTD
 (MANAGER)