

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	09 Jun 2020 Edit Reg		08 Jun 2020 00:00 Edit Adj Rpt	S\$1,660.00 Edit Estimates	S\$1,660.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	FENGSHENG ELECTRIC CO PTE LTD , Co. Reg. No.: A198301832C								
Main Claimant:	SMRT TAXIS PTE LTD , Co. Reg. No.: 198905369K								
Vehicle Reg. No.:	SHD6470X	Date of Loss:	05/06/2020 07:00 - :59 [31 Months and 2 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 1287997973SG	Policy/Cover Note No.:	1900130213 (Comprehensive) Coverage: 23/07/2019 - 22/07/2020						
Vehicle Reg. No. (Insured):	GBJ6873G	Policy No. (Claimant):							
		Excess:							
Repairer:	SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4, 757705 Woodlands - Tel: 68662628								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Loh, Chee-Heng] Chee-Heng.Loh@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by OI SUN PIN] ... [Final Rpt due 18/06/2020]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
AIG_SG_EXPRESS (05/10/2020): Alert - Adj Mandate Approved (S\$2314.28) - SHD6470X - Claim Handler: Loh, Chee-H...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SHD6470X (1287997973SG)**
[GBJ6873G]
TP
SMRT TAXIS PTE LTD
Jun 5 2020 7:00AM
[FENGSHENG ELECTRIC CO PTE LTD]
SMRT Automotive Services Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[Upload Video](#)
[Upload Audio](#)

View View in Browser ▼

Video				1 per page ▼	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	15/09/20 11:35	Video - Accident	1	Load MP4	

Letters/Correspondences				1 per page ▼	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown	1	Edit	

Photos/Images				3 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	29/06/20 16:13	Chassis Number	1	Load JPG	☒
2	29/06/20 16:13	Odometer Reading	1	Load JPG	☒
3	29/06/20 16:13	General View	1	Load JPG	☒
4	29/06/20 16:13	General View	1	Load JPG	☒
5	29/06/20 16:13	General View	1	Load JPG	☒
6	29/06/20 16:13	General View	1	Load JPG	☒
7	29/06/20 16:13	General View	1	Load JPG	☒
8	29/06/20 16:13	General View	1	Load JPG	☒
9	29/06/20 16:13	General View	1	Load JPG	☒
10	29/06/20 16:13	General View	1	Load JPG	☒
11	29/06/20 16:13	General View	1	Load JPG	☒
12	29/06/20 16:13	General View	1	Load JPG	☒
13	29/06/20 16:13	General View	1	Load JPG	☒
14	29/06/20 16:13	General View	1	Load JPG	☒
15	29/06/20 16:13	General View	1	Load JPG	☒
16	29/06/20 16:13	General View	1	Load JPG	☒
17	29/06/20 16:13	General View	1	Load JPG	☒
18	29/06/20 16:13	General View	1	Load JPG	☒
19	29/06/20 16:13	General View	1	Load JPG	☒
20	29/06/20 16:13	General View	1	Load JPG	☒
21	29/06/20 16:13	General View	1	Load JPG	☒
22	29/06/20 16:13	General View	1	Load JPG	☒
23	29/06/20 16:13	General View	1	Load JPG	☒
24	29/06/20 16:13	General View	1	Load JPG	☒
25	29/06/20 16:13	General View	1	Load JPG	☒
26	29/06/20 16:13	General View	1	Load JPG	☒
27	29/06/20 16:13	General View	1	Load JPG	☒
28	29/06/20 16:13	After Repair Photo	1	Load JPG	☒
29	29/06/20 16:13	After Repair Photo	1	Load JPG	☒
30	29/06/20 16:13	After Repair Photo	1	Load JPG	☒
31	29/06/20 16:13	After Repair Photo	1	Load JPG	☒

Documentation				1 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print

Video			1 per page ▾	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail Print
1	09/06/20 11:29	TP ESTIMATE-MARKED		Load PDF
2	09/06/20 11:29	TP GIA REPORT		Load PDF
3	10/06/20 11:32	Status of Driving Licence		Load PDF
4	02/10/20 14:23	LETTER TO OI		Load PDF
5	02/10/20 14:23	LOD		Load PDF
6	02/10/20 14:23	LTA SEARCH FEE		Load PDF
7	09/10/20 15:54	Authorisation to Act		Load PDF
8	09/10/20 15:54	Release Voucher		Load PDF
9	09/10/20 15:54	RENTAL MILEAGE		Load PDF
10	09/10/20 15:54	RENTAL RECEIPT		Load PDF
11	09/10/20 15:54	WORKSHOP INVOICE		Load PDF
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail Print
1	10/06/20 11:28	OI GIA REPORT		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST

ResetSavePrint

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	GBJ6873G (Insd veh)	Model:	TOYOTA PRIUS HYBRID 1.8
	SHD6470X (TP veh)		CVT (A)
Date of Accident:	05/06/2020		

Global Sum Settlement	:	[]	Yes	[X]	No	
Repair Estimate	:	\$				12,022.64
Final Repair Cost	:	\$				1,660.00
Loss of Use	:	\$				200.00
Rental (if any)	:	\$				447.28
LTA / GIA Search Fee	:	\$				7.00
Others:	:	\$				
	:	\$				
Final Settlement Sum	:	\$				2,314.28

Is Third Party Workshop GIA Registered?				[]	YES	[X]	NO	(Kindly indicate below)
A) For Non GIA Registered Workshop:				Agreed Liability _____ 100 _____ (%)				
B) For GIA Registered Workshop:				BOLA Applicable: Yes/ No BOLA Scenario No: _____				
BOLA Liability: _____ (%)				Assessed Liability (*): _____ (%)				
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.								
Remarks _____								

Payment Instruction: Payee's Breakdown			
1)	SMRT TAXIS PTE LTD	: \$	2,314.28
2)		: \$	
3)		: \$	
4)		: \$	

NUR SHAQILAH BTE ABDOL WAHAB

LKK Auto Consultants Pte Ltd

09 Oct
2020

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG20006291/QDS3S2**Date:** 09/10/2020REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900130213
Claimant Vehicle No :	SHD6470X	Insured Vehicle No :	GBJ6873G
Date of Loss:	05/06/2020	Nature of Claim:	TP
		Claim No:	1287997973SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD6470X		
Make & Model:	TOYOTA PRIUS HYBRID, 1.8 CVT (A)	Engine No:	2ZRS101962
Reg. Date:	03/11/2017 (Man. Year: 2017)	Chassis No:	JTDKB3FU103573678
Colour:	Maroon	Odometer:	212719 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,816.64	180.00	7,636.64	97.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,206.00	1,480.00	2,726.00	64.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	12,022.64	1,660.00	10,362.64	86.19
+ Loss of Use (4.0 x S\$50.00/day) (S\$)		200.00		
+ Car Rental (4.0 x S\$111.82/day) (S\$)		447.28		
+ Doc/Search Fee (S\$)		7.00		
Nett Liability (S\$)		2,314.28		

INSPECTION

Date of Assignment:	08/06/2020	
Date Inspected:	08/06/2020	Inspected At: SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4 Singapore 757705
Estimated Period of Repair:	3.0 days	

Adjuster: OI SUN PIN**Manager:** CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*PIXEL STICKER	Necessary	120.00 F	*120.00 F
2	1		*STICKER DECAL SMRT (DOOR)	Necessary	60.00 F	*60.00 F
3	1		*CLIPS PIECE, FRT & RR BUMPER	Serviceable	1.50 F	*- F
4	1		*PAD, RR BUMPER, RH & LH, 1	Serviceable	3.80 F	*- F
5	1		*PAD, RR BUMPER, RH & LH, 2	Serviceable	3.80 F	*- F
6	1		*PAD, RR BUMPER, RH & LH, 3	Serviceable	3.80 F	*- F
7	1		*SEAL, RR BUMPER ARM, RH & LH	Serviceable	11.00 F	*- F
8	1		*RETAINER, RR BUMPER, LH	Serviceable	111.50 F	*- F
9	1		*FILLER, RR BUMPER, LH	Serviceable	119.90 F	*- F
10	1		*SEAL, RR BUMPER, LH	Serviceable	85.20 F	*- F
11	1		*PANEL SUB-ASSY, FRONT DOOR LH	Serviceable	1,249.60 F	*- F
12	1		*WEATHERSTRIP, REAR DOOR, NO.2, LH	Serviceable	33.20 F	*- F
13	1		*DOOR LOCK REAR, LH	Serviceable	544.70 F	*- F
14	1		*DOOR LOCK STRIKER	Serviceable	38.00 F	*- F
15	1		*HINGE ASSY, REAR DOOR, UPPER LH	Serviceable	83.30 F	*- F
16	1		*HINGE ASSY, REAR DOOR, LOWER LH	Serviceable	73.30 F	*- F
17	1		*CHECK ASSY, REAR DOOR	Serviceable	153.50 F	*- F
18	1		*LINER, REAR FENDER, LH	Serviceable	135.80 F	*- F
19	1		*TYRE	Serviceable	126.74 F	*- F
20	1		*COVER, RR BUMPER ASSY	Repair	423.90 F	*- F
21	1		*COVER, REAR FLOOR UNDER, LH	Repair	234.30 F	*- F
22	1		*MOULDING ASSY, BODY ROCKER PANEL, LH	Repair	576.00 F	*- F
23	1		*PANEL SUB-ASSY, REAR DOOR, LH	Repair	1,243.90 F	*- F
24	1		*PANEL SUB-ASSY, FENDER REAR LH	Repair	824.80 F	*- F
25	1		*WHEEL, DISC	Repair	1,555.10 F	*- F
F=Franchise part.						
					Total Parts (\$\$)	7,816.64 180.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING & BODYWORK.	New	1,014.00	500.00
2	SPRAY PAINT.	New	2,052.00	830.00
3	TO CHECK WIRING AND SYSTEM FUNCTION.	New	80.00	20.00
4	TO APPLY RUST-PROOFING PN AFFECTED AREA.	New	100.00	30.00
5	TO DO WHEEL ALIGNMENT / TYRE BALANCING.	New	120.00	60.00
6	TO REMOVE / REFIT SEAT.	New	120.00	0.00
7	TO TRANSFER DOOR MECHANISM.	New	120.00	0.00
8	TO TEST AND REFIX REVERSE SENSOR SYSTEM.	New	120.00	20.00
9	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE).	New	120.00	20.00
10	TO REMOVE AND REFIT WIRE HARDESS.	New	200.00	0.00
11	TO REPLACE SUNDRY PARTS.	New	100.00	0.00
12	TO WASH AND VACUUM.	New	60.00	0.00
Gross Labour Cost (\$\$)			4,206.00	1,480.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >