



## Section A - Accident Details

Registration Number	SHD6470X
Case Reference Number	TAX/06/20/2006
Registration Date	3/11/2017
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	MOHAMED RAMDAN BIN MOHAMED YUSOF
Type of Accident	Head To Side
Accident Date and Time	5/6/2020 7:15 AM
Accident Reported Date and Time	5/6/2020 8:39 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24107121
Special Instruction to ARC, if any	TP / LEFT PORTION
Prepared Date and Time	5/6/2020 1:37 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

## Section B - Summary of Repair Estimates

## Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,014.00	\$500.00
Total Spray Cost	\$2,052.00	\$830.00
Total Spare Part Cost	\$6,047.80	\$180.00
Total Other Cost	\$1,140.00	\$150.00
<b>TOTAL COST</b>	<b>\$10,253.80</b>	<b>\$1,660.00 (P/P)</b>
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	8.0	3.0
Prepared / Adjusted By	Tuck Foo Kok	Sun Pin (LKK) / AIG
ARC / Surveyor Sign Off Date	05/06/2020 2:58 PM	08/06/2020 2:18 PM
Signature		
Remarks	P/P, before paint photo.	

## Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2006-0314	Invoice Number	
Quotation Date	22.06.2020	Invoice Date	
Invoice Amount		Prepared Date	

## Section D - Details of Repair Estimates

## Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR LH PORTION	\$1,014.00	\$500.00
Total Labour	\$1,014.00	\$500.00

## Part 2 - Spray Painting &amp; Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT DOOR LH	\$378.00	\$0.00
TO RESRAY REAR DOOR LH	\$378.00	\$200.00
TO RESPRAY ROCKER PANEL MOULDING	\$180.00	\$100.00
TO RESPRAY RIM	\$180.00	\$50.00
TO RESPRAY REAR FENDER LH	\$378.00	\$200.00
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY FILLER RR BUMPER LH	\$180.00	\$80.00
Total Spray Painting & Panel Beating	\$2,052.00	\$830.00

## Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$30.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$60.00
TO REMOVE / REFIT SEAT	\$120.00	\$0.00
TO TRANSFER DOOR MECHANISM	\$120.00	\$0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$20.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$120.00	\$20.00
TO REMOVE AND REFIT WIRE HARDESS	\$200.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$1,140.00	\$150.00

## Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		5215947913	COVER, RR BUMPER ASSY	1.00	\$423.90	100.00	\$0.00	Replace	Repair
		5216116010	CLIPS PIECE, FRT & RR BUMPER	0.00	\$1.50	0.00	\$0.00	Replace	Not Given
		5246247030	PAD, RR BUMPER, RH & LH, 1	0.00	\$3.80	0.00	\$0.00	Replace	Not Given
		5246247020	PAD, RR BUMPER, RH & LH, 2	0.00	\$3.80	0.00	\$0.00	Replace	Not Given
		5246247010	PAD, RR BUMPER, RH & LH, 3	0.00	\$3.80	0.00	\$0.00	Replace	Not Given
		5219147030	SEAL, RR BUMPER ARM, RH & LH	0.00	\$11.00	0.00	\$0.00	Replace	Not Given
			PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace

SVC

SVC

SVC

SVC

SVC

NEC

# SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 19/06/2020

User ID : PohSuan

5257647040	RETAINER, RR BUMPER, LH	0.00	\$111.50	0.00	\$0.00	Replace	Not Given <input checked="" type="checkbox"/>	SVC
5256647900	FILLER, RR BUMPER, LH	0.00	\$119.90	0.00	\$0.00	Replace	Not Given <input checked="" type="checkbox"/>	SVC
5839947030	COVER, REAR FLOOR UNDER, LH	1.00	\$234.30	100.00	\$0.00	Replace	Repair <input checked="" type="checkbox"/>	
5259247040	SEAL, RR BUMPER, LH	0.00	\$85.20	0.00	\$0.00	Replace	Not Given <input checked="" type="checkbox"/>	SVC
6700247162	PANEL SUB-ASSY, FRONT DOOR LH	0.00	\$1,249.60	0.00	\$0.00	Replace	Not Given <input checked="" type="checkbox"/>	SVC
	STICKER DECAL SMRT (DOOR)	1.00	\$60.00	0.00	\$60.00	Replace	Replace <input checked="" type="checkbox"/>	NEC
7586047900	MOULDING ASSY, BODY ROCKER PANEL, LH	1.00	\$576.00	100.00	\$0.00	Replace	Repair <input checked="" type="checkbox"/>	
6700447210	PANEL SUB-ASSY, REAR DOOR, LH	1.00	\$1,243.90	100.00	\$0.00	Replace	Repair <input checked="" type="checkbox"/>	
6789647010	WEATHERSTRIP, REAR DOOR, NO.2, LH	0.00	\$33.20	0.00	\$0.00	Replace	Not Given <input checked="" type="checkbox"/>	SVC
6906052280	DOOR LOCK REAR, LH	0.00	\$544.70	0.00	\$0.00	Replace	Not Given <input checked="" type="checkbox"/>	SVC
6941020110	DOOR LOCK STRIKER	0.00	\$38.00	0.00	\$0.00	Replace	Not Given <input checked="" type="checkbox"/>	SVC
6876020122	HINGE ASSY, REAR DOOR, UPPER LH	0.00	\$83.30	0.00	\$0.00	Replace	Not Given <input checked="" type="checkbox"/>	SVC
6878052031	HINGE ASSY, REAR DOOR, LOWER LH	0.00	\$73.30	0.00	\$0.00	Replace	Not Given <input checked="" type="checkbox"/>	SVC
6863047050	CHECK ASSY, REAR DOOR	0.00	\$153.50	0.00	\$0.00	Replace	Not Given <input checked="" type="checkbox"/>	SVC
6160247160	PANEL SUB-ASSY, FENDER REAR LH	1.00	\$824.80	100.00	\$0.00	Replace	Repair <input checked="" type="checkbox"/>	
6563847060	LINER, REAR FENDER, LH	0.00	\$135.80	0.00	\$0.00	Replace	Not Given <input checked="" type="checkbox"/>	SVC
	TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given <input checked="" type="checkbox"/>	SVC
4261147450	WHEEL, DISC	1.00	\$1,555.10	100.00	\$0.00	Replace	Repair <input checked="" type="checkbox"/>	
Total			\$7,756.64		\$180.00			

## Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

180.00 /  
+ 500.00 /  
+ 980.00 /  
-----  
1660.00 /

P/P

3 days