



**National Assessment Centre Services**  
 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933  
 TEL: 6841 0055 FAX: 6841 6315  
 Reg. No: 52983356E GST Reg. No. 20-0405911-H



**TAX INVOICE**

NTUC INCOME INSURANCE CO-OPERATIVE LTD INV No. NA2003139  
 73 BRAS BASAH ROAD  
 #05-01 NTUC TRADE UNION HOUSE INV Date 23/06/2020  
 SINGAPORE 189556 Reference NS/INC20006292/T1sf3n2  
 Code INC4



**PROFESSIONAL SERVICE FEE**

Vehicle No. SHD 4955C  
 Insured Veh. SMN 6178D  
 Claim No. MT/1094143-002  
 Policy No. 5110949422  
 Accident Date 09/06/2020  
 Inspection Date 10/06/2020

Description	Total
Survey Inspection	160.00
Resurvey Inspection	
Digital Photographs	
Transportation	
<b>Subtotal</b>	<b>160.00</b>
<b>GST (7%)</b>	<b>11.20</b>
<b>Grand Total</b>	<b>171.20</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'National Assessment Centre Services'**

**National Assessment Centre Services**





# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC20006292/T1sf3n2	
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556	Date: 23-06-2020
Code: INC4	



### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	SMN 6178D	<b>Veh. Inspected</b>	SHD 4955C
<b>Policy No.</b>	5110949422	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	MT/1094143-002	<b>Excess (\$)</b>	0.00
<b>Assign From</b>		<b>Assign Date</b>	10/06/2020

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	HYUNDAI I40	<b>c.c</b>	1685
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2014
<b>Chassis No.</b>	KMHLB41UMEU057767	<b>Colour</b>	BLUE
<b>Odometer</b>	421764	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
<b>General</b>	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	205/60 R16	WEST LAKE	6 mm
<b>L/H Front Tyre</b>	205/60 R16	WEST LAKE	6 mm
<b>R/H Rear Tyre</b>	205/60 R16	WEST LAKE	6 mm
<b>L/H Rear Tyre</b>	205/60 R16	WEST LAKE	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	09/06/2020	<b>Inspection Date</b>	10/06/2020
<b>Survey held at</b>	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **3 Working Days**



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 4955C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	I40V2 COVER-FR BUMPER	DEFORMED	1,052.20	1,052.20
1	I40VC BRKT ASSY-FR BPR UP	DEFORMED	22.40	22.40
1	I40VC BRACKET-FR BUMPER S	NOT NECESSARY	24.60	-
10	HYUNDAI BUMPER COVER CLIP	NECESSARY	22.00	22.00
1	I40VC LAMP ASSY-HEAD LH	CRACKED	1,388.00	1,388.00
1	I40VC PANEL ASSY-HOOD	TO REPAIR SEE LABOUR	2,265.90	-
1	I40VC PANEL-FENDER LH	BENT	663.00	663.00
1	I40V2 GUARD ASSY-FR WHEEL	DEFORMED	174.90	174.90
1	I40VC CAP ASSY-WHEEL HUB	DEFORMED	112.50	112.50
	LESS 20% DISCOUNT		-1,145.10	-687.00
			4,580.40	2,748.00
<b><u>SPECIAL NETT ITEMS</u></b>				
1	FRT FENDER ADVERTISEMENT LOGO LH (SN)	NECESSARY	100.00	100.00
			100.00	100.00
<b><u>LABOUR</u></b>				
	TOWING FEE.		60.00	-
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF I40VC PANEL ASSY-HOOD.		700.00	560.00
	SPRAYPAINT ON AFFECTED AREA.		750.00	600.00
	CHECK ALL LIGHTING.		50.00	30.00
	TUFF COAT ON AFFECTED PARTS.		50.00	30.00
	ADJUST FRONT WHEEL ALIGNMENT.		80.00	60.00
	-		-	-
	-		-	-
	-		-	-
			1,690.00	1,280.00
<b>GRAND TOTAL</b>			<b>6,370.40</b>	<b>4,128.00</b>

<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)</b>			<b>3,300.00</b>
---	--	--	-----------------

Report Ref No. NS/INC20006292/T1sf3n2



**MOHAMAD TAUFIKH**

**M.MATAI, AMSAE-A**

**Automotive Assessor**



**K.K.LAU CPT(RET)**

**BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE**

**REGD Auto Consultant-SAE, Licensed Appraiser**

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

**No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.**



# National Assessment Centre Services


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H

PHOTOGRAPHS FOR VEHICLE NO. SHD 4955C

INSPECTION





## National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H





## National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H





# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H





## National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H





## National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H





## National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H

PHOTOGRAPHS FOR VEHICLE NO. SHD 4955C

RE-INSPECTION

