

176 Sin Ming Drive #01-10
 Sin Ming AutoCare Singapore 575721
 Tel No. : 6452 6657 Fax No. : 6451 4618
 E-Mail : autosoon1@gmail.com
 Tax Reg. No. : 200709808N Buss. Reg. No. : 200709808N

CHINA TAIPING INSURANCE (S) PTE LTD
 3 Anson Rd, #16-00
 Springleaf Tower
 Singapore 079909

Attention : Motor Claim Department

Contact : +65 6389 6111 Fax No. : +65 6222 1033

Estimate : ES000439

Date : 05/06/2020

Vehicle Num. : SKS 9790 M

Make/Model : NISSAN URVAN NV350-2015

Chassis/Eng# : JN1UC4E26Z0002290

Accident Date : 05/06/2020

Claim No. :

Reference : OD/01/06/20

Policy No. : DMCVSNA00000712000

S/N	Quantity	Particular	Unit Price	Amount S\$
1.	1	NETT ITEMS :		
2.	1	Windscreen panel assy ✓ BUC		
3.	1	Windscreen panel garnish ✓ CRA	1,350.20	946.14
4.	1	Wiper motor panel ✓ BT	206.80	145.76
5.	1	Wiper linkage panel assy X NN	164.30	115.01
6.	1	Instrument support reinforcement assy ✓ BT	416.30	X
7.	1	Radiator grille assy ✓ CRA	499.30	349.51
8.	1	Radiator grille emblem ✓ REC	521.50	364.7
9.	1	Bumper facial	79.90	55.93
10.	6	Bumper facial clips Dis MC	943.70	660.59
11.	1	Bumper reinforcement assy TN	3.80	22.80
12.	2	Bumper side retainer MC CRA ✓	181.00	987.00
13.	1	O/s fog lamp assy ✓ CRA	362.00	690
14.	1	O/s fog lamp cover ✓ CRA	311.80	123.4
15.	1	O/s head lamp assy ✓ Dis	120.70	218.3
16.	1	O/s panel assy ✓ BUC	443.30	84
17.	1	Turbo charger intercooler hose ✓ CT	534.60	310.31
18.	1	Steering column assy ✓ JM	80.00	373.8
19.	1	Pedals combination bracket ✓ BT	1,354.00	56
			189.30	947.8
				132.5
		Nett Total S\$:		8,587.50
		10.00% Discount S\$:		858.75
				7,728.75
		SPECIAL NETT ITEMS :		
1.	1	Turbo charger intercooler assy ✓ Dis	2,121.60	1909.44
		Special Nett Total S\$:		2,121.60

AutoSoon Pte Ltd

Page 2/2

Ming Drive #01-10
 100 AutoCare Singapore 575721
 Tel : 6452 6657 Fax No. : 6451 4618
 Email : autosoon1@gmail.com
 Reg. No. : 200709808N Buss. Reg. No. : 200709808N

CHINA TAIPING INSURANCE (S) PTE LTD
 3 Anson Rd, #16-00
 Springleaf Tower
 Singapore 079909

Attention : Motor Claim Department
 Contact : +65 6389 6111 Fax No. : +65 6222 1033

Estimate : ES000439

Date : 05/06/2020
 Vehicle Num. : SKS 9790 M
 Make/Model : NISSAN URVAN NV350 2015
 Chassis/Eng# : JN1UC4E28Z0002290
 Accident Date : 05/06/2020
 Claim No. :
 Reference : OD/01/06/20
 Policy No. : DMCVSHA00000712000

S/N	Quantity	Particular	Unit Price	Amount S\$
		LABOUR :		
2		To supply windscreen sealant and dam rubber	90.00	180.00
1		To remove windscreen to facilitate replace panels	150.00	150.00
1		To remove instrument board, steering column, pedals to facilitate cut/hot works and weld panels	280.00	280.00
1		To remove interior air con evaporator, heat exchanger coil, blower motor housing to replace panels/refill gas	280.00	280.00
1		To rewire affected section and refocus head lamp beam	80.00	80.00
1		To putty and respray damaged front section include door	850.00	850.00
1		To cut/remove damaged panel, restraighen/recondition windscreen pillars, front chassis crossmember include weld/fix replace/realign bumper and panels in repair	1,400.00	1,400.00
1		To remove and replace turbo charges intercooler	50.00	50.00
1		To computer wheel realignment after refix steering assy	80.00	80.00
1		To tow ambulance on dolly wheels, receipt enclosed	100.00	100.00
		Labour Total S\$:		3,450.00
			12204.81	2250
		+10%:	13425.29	
			15675.29	

Total S\$: 13,300.35

AutoSoon Pte Ltd

Kindly note above mentioned parts are visible quoted, we reserve our right to submit further quote if further parts are found damaged while undergoing repair.

Date Survey: Surveyor Name: Co Name:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

8 Days
 part by part
 before part photos
 Guo Qiang
 82880282
 12/6/2020
 Not Autharised
 Excess \$1000.