

							ENGINEERING
Our J	lob Re	f No		4034524		Com	fortDelGro Engineering Pte Ltd
Date		:	09	9/06/20		59 L	oyang Drive Singapore 508969 6546 8156
FINA	LIZAT	ION FOI	RM				
То	: _			LKK		Fax :	
Attn	4			TAUFIK			
			SH 89	962D		DOA	07/06/20
The s	survey	and esti	mates of	the repairs of the ab	ove-mentione	d vehicle are a	as follows:-
1.	The r	epair job	shall bill	to:	NTUC		SJU5926S
2.	The f	inalized	amount s	shall be:		###	
	(a)			er List discount			
	(b)		Charges		<del>    </del>	ŧ	
	(5)		_	By-Part Repair Cos			
		. 0.0.	01 1 411 2	y r arr repair coo	•	N	###
	(c.)	Total fo	or Lumps	ir (if applicable) um repair cost after	Less: 20%	- Ki	\$1,200.00
		Final L	.umpsun	n Repair cost			
3. 4.	We s	hall trea				rking days	is no reply from you
5.	Thanl	k you for	your ass	istance.		e confirm the oalized amount	estimates and
	Signa			M	-	gnature:	fought Tanlikh
	Name	-	IUMANI	5	_	me :	<del>. 0</del>
	Tel		3214 831		– Da	te :	10/6/20
	Fax	: 6	5546815	6	-		
For O	fficial	Use On	ly				
		ltem		Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Re	ntal R	ate P/Da	ıy		YES		
2. Lo	ss of Ir	ncome P	aid		N		
3. Su	rvey F	ees					
		rch Fee		\$7.49			
		ees (on if applica					
	errun						
Rema	rks:						



VEHICLE NO. :	SH 8962D	TYPE OF CASE	•	NTUC
JOBCARD NO.	305403452	SURVEY BY	•	LKK-TAUFIQ
ACC.DATE	07/06/20	DATE	:	>

DESCRIPTION	QTY	ESTIMATE	REMARKS
REAR BUMPER SIDE BRACKET LH	1	\$36.50	cra v
CHECK ITEM	+++		
ABOUR			
	-		
	-		
	+		
	TOTAL:	\$36.50	JUMANI