

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

NUMC-JU 6450

Date: 08.06.2020
Time: 13:41:49
Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305403452
REGN NO : SH 8962D
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 16.07.2015
DATE/TIME IN : 08.06.2020 10:15
ACCIDENT DATE : 07.06.2020

JOB PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0103-0579-G	I40VC COVER ASSY-RR BUMPE	1	1,106.00	20.00	884.80	de
0002	04-01-0103-0738-G	I40VC COVER-RR BUMPER LWR	1	228.00	20.00	182.40	Rx
0003	04-01-0103-0739-G	I40VC ABSORBER-RR BUMPER	1	119.50	20.00	95.60	7 X un
0004	04-01-0103-0740-G	I40VC BEAM-RR BUMPER#	1	428.40	20.00	342.72	7 X un
0005	04-01-0101-0111-G	HYUNDAI BUMPER COVER CLIP	10 L	22.00	20.00	17.60	wa
0006	04-01-0103-1150-A	I40VC PROTECTOR MAT	1 N	50.00	2.00	50.00	na
Supp side bracket LH 36.5 20% = 29.20							
SUB-TOTAL : 1,573.12							

JOB NATURE

0000	PB	PANEL BEATING	300.00	280
0001	SP	SPRAYPAINT CHARGE	300.00	200
0002	L	REMOVE REFIX REVERSE SENSOR	80.00	30 510
SUB-TOTAL :			680.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

taupkin 97495745
wp' 8/6/20 @ 350 pu
Lumpsum 02 days
Resurvey after repair
taupkin @ lkk auto-wn
981.60
510
1491.60
4/5/1200
2 days ff