



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 7348B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR BUMPER	DEFORMED	458.60	458.60
1	REAR BUMPER SIDE RETAINER RH	DEFORMED	112.70	112.70
1	REAR BUMPER LOWER COVER	DEFORMED	552.60	552.60
1	REAR BUMPER REFLECTOR RH	CRACKED	142.00	142.00
1	REAR BUMPER TOWING COVER	DEFORMED	82.70	82.70
1	REAR BUMPER UNDER SIDE COVER RH	NOT NECESSARY	232.00	-
1	REAR REINFORCEMENT	NOT NECESSARY	318.80	-
1	REAR BUMPER STAY RH	NOT NECESSARY	139.60	-
10	REAR BUMPER CLIPS @\$2.50	NECESSARY	25.00	25.00
1	REAR TRUNK HYBRID EMBLEM	NECESSARY	52.40	52.40
1	REAR TRUNK PRIUS EMBLEM	NECESSARY	52.40	52.40
1	REAR EXHAUST PIPE	TO REPAIR SEE LABOUR	1,163.40	-
1	REAR EXHAUST PIPE INSULATOR	NOT NECESSARY	314.60	-
	LESS 25% DISCOUNT		-911.70	-369.61
			2,735.10	1,108.79
<b><u>NETT ITEMS</u></b>				
1	REAR TRUNK APP COMFORT STICKER (N)	NECESSARY	40.00	40.00
1	REAR TRUNK COMFORT & TEL NO. STICKER (N)	NECESSARY	60.00	60.00
1	REAR REVERSE SENSOR (N)	NOT NECESSARY	135.70	-
	LESS 10% DISCOUNT		-23.57	-10.00
			212.13	90.00
<b><u>LABOUR</u></b>				
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR EXHAUST PIPE.		1,050.00	640.00
	SPRAY PAINTING CHARGE.		600.00	400.00
	TUFF KOTE.	NOT NECESSARY	90.00	-
	CHECK LIGHTING.		60.00	30.00
	REMOVE / REFIX REVERSE SENSOR.		90.00	30.00
			1,890.00	1,100.00

Report Ref No. NS/INC20006299/T1vf3e2

GRAND TOTAL		4,837.23	2,298.79
RECOMMENDED COST OF REPAIRS (CONFIRMED)			2,298.79

Report Ref No. NS/INC20006299/T1vf3e2



MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.