



TRANS EUROKARS PTE LTD



ESTIMATE COST OF REPAIRS

FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSE SINGAPORE 068877 ATTN.: MOTOR CLAIMS FAX:		NAME: Mr Elango S/O Kanakasabai Padayach ADDRESS: Blk 514 Jelapang Road #09-237 Singapore 670514 TEL: 90250078		WIP: 12441 EXCESS: DATE: 8-Jun-20	
VEH NO:	SJX9876K	DATE IN:		CONTACT PERSON:	Jobi 63310682
CHASSIS NO:	JM6GL1072K0318117	MILEAGE:		TYPE OF CLAIM:	THIRD PARTY CLAIM
MODEL:	MAZDA6	DATE REG.:	25-Feb-20	POLICY NO.:	
NATURE OF WORKS					
Parts Description					
NO	QTY			REVISED	PRICES
1	REAR BUMPER <i>de /</i>	1	MGSK1-50-221ABB		\$ 1,099.00
2	BRACKET CENTER <i>?</i>	1	MKD53-50-251		\$ 5.40
3	TOWING COVER LHS <i>mis /</i>	1	MGSH7-50-EL1 BB		\$ 48.90
4	COVER UNDER, REAR BUMPER <i>?</i>	1	MGSH7-50-C51		\$ 122.20
5	REAR REINFORCEMENT <i>?</i>	1	MGHK1-50-260		\$ 538.30
6	GROMMET, REAR BUMPER <i>new /</i>	4	MBHN1-50-021A		\$ 10.80
7	GROMMET, REAR BUMPER <i>new /</i>	2	M9991-00-501		\$ 6.00
8	CLIP, REAR BUMPER <i>new /</i>	4	MC274-50-133		\$ 14.80
9	RUBBER SEAL, REAR BUMPER <i>new /</i>	2	MGSH7-50-2G1		\$ 27.40
10	RIVET, REAR BUMPER <i>new /</i>	2	MTK21-50-355		\$ 18.40
11	RIVET, REAR BUMPER <i>new /</i>	6	MEA01-50-037		\$ 48.00
12	FASTENER, REAR BUMPER <i>new /</i>	6	MB45A-56-146A		\$ 18.00
13	RETAINER CENTER, SENSOR <i>?</i>	2	MKD45-67-UC5A2Y		\$ 31.00
14	SENSOR CENTER, ULTRASONIC <i>?</i>	2	MGMK6-67-UC1 2Y		\$ 361.80
15	TAPE PROTECTOR, SENSOR <i>new /</i>	4	MBCKA-50-EM1		\$ 18.80
16	REFLECTOR LHS <i>?</i>	1	MGRF5-51-5M0A		\$ 41.10
17	GASKET LHS, TAILLAMP <i>new /</i>	1	MGRF5-51-163		\$ 46.00
18	GASKET RHS, TAILLAMP <i>new /</i>	1	MGRF5-51-153		\$ 46.00
TOTAL PARTS					\$ 2,501.90
TOTAL PARTS COST					\$ 2,501.90
Labour Description					
1	MZ-BR-REAR02	TO REPLACE REAR BUMPER AND REAR REINFORCEMENT. REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.			<i>660</i> \$ 1,320.00
2	MZ-SP-SREAR2	TO RESPRAY REAR BUMPER AND REAR REINFORCEMENT.			<i>630</i> \$ 1,260.00

3	MZ-BR-REVSER	TO TRANSFER REVERSE SENSORS.	NETT	\$ 330.00
4	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.	X	\$ 250.00
5	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	150	\$ 250.00
6	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	180	\$ 350.00
7	MZ-BR-SUNDRI	SUNDRIES.	20	NETT \$ 100.00

TOTAL LABOUR	\$ -	\$ 3,860.00
TOTAL PARTS	\$ -	\$ 2,501.90
TOTAL	\$ -	\$ 6,361.90
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	
GST 7%	\$ -	\$ -
GRAND TOTAL	\$ -	\$ -

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

TRANS EUROKARS PTE LTD

Authorized Signature

R. A. S. M.
Hp 90010068
3 days
10/06/2020 @ 1425
Reay before paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: