

ASS. REG. BY:

REF:

LPC /

ASSIGNMENT

08 15

From:

Date:

Estimated Cost:

Veh No:

YN 8545Y

Yr Regn:

08 29

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

JUZU

NPR 75

c.c.

5193

Colour:

Green

A/C:

Insured / Std / NI / NA

Sp. Reading:

194827

T/Radio:

Insured / Std / NI / NA

Eng/No:

JAA NPR 7511K

7104330

C/No:

686

1140852

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

B.S

215/75 R17.5

T/Ring

(D)

BS / DUN / EXNOVA / GY / FS / LIZA / MIG / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

9

9 mm

L/Bal.

9

mm

L/Bal.

9

9 mm

D.O.A.

1/6/20

D.O.I.

11/6/2020

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

FR N/S, Rear & UIC

The UIC / Chassis frame / Body Structure affected due to collision.

OD / TP / WS / TP RES / QD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s:

S&H

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

700

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

\$34K

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

18

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP.

24 HRS

Date:

8/24

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

likely to have supplementary items.

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS + SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

INSURER: **Lonpac Insurance Bhd (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (Own Damage)	Ref. No:	
Policy No:	Z19VC05002971	Date of Loss:	01/08/2015
Vehicle Reg. No.:	YN8545Y	Driveable?	
Driver Age/Info:	31 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved:	
Insured/Claimant:	YEW HUAT SCAFFOLDING & CONSTRUCTION PTE LTD		
Driver:	DEVARAJ NALLUSAMY		

Make/Model:	ISUZU NPR75UH5A, 5.2 D (M)	Vehicle Reg. Date:	11/08/2015
Vehicle Colour:	Green	Chassis No:	JAANPR75HF7104330
Engine No:	4HK1357154		
Odometer:	194827 KM		

Paint Type:
Total Loss? **NO**
Est. Duration of Repair (day) **28 18 days**

*Not Authorised
11/8/15
Moving After Palm Ex 8700/*

Description of Accident/Loss **REFER ATTACHED REPORT.**
Present Location: **S & H MOTOR PTE LTD (SIN MING)**

COST OF CLAIMS

Parts		Amount
Miscellaneous Items		
Labour		
Paintwork Labour		
Towing		

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer	Gross Total (\$\$)	13,252.25
Signature:	+ GST 7.00% (\$\$)	927.66
Date:	Nett Amount (\$\$)	14,179.91

This claim is handled by: **LUM WEE KEAT**

Generated using Merimen e-Claims Internet Estimation & Adjusting System



INSURER: Lonpac Insurance Bhd (HQ)

PARTICULARS OF CLAIM

Claim Type: OD (Own Damage)
Policy No: Z19VC05002971
Vehicle Reg. No.: YN8545Y
Driver Age/Info: 31 / MALE
TP Injury Involved? NO
Insured/Claimant: YEW HUAT SCAFFOLDING & CONSTRUCTION PTE LTD
Driver: DEVARAJ NALLUSAMY

Ref. No:
Date of Loss: 01/06/20
Driveable?
Party At Fault: UNKNOWN
Third Party Involved:

Make/Model: ISUZU NPR75UH5A, 5.2 D (M) Vehicle Reg. Date: 11/08/2015
Vehicle Colour: Green
Engine No: 4HK1357154 Chassis No: JAANPR75HF7104330
Odometer: 194827 KM

Paint Type:
Total Loss? NO
Est. Duration of Repair (day) 28 18 days

*Not Authorized
11/06/20
Survey After Paint ex 8700*

Description of Accident/Loss REFER ATTACHED REPORT.
Present Location: S & H MOTOR PTE LTD (SIN MING)

COST OF CLAIMS

	Amount
Parts	5,859.25
Miscellaneous Items	1,388.00
Labour	5,925.00
Paintwork Labour	0.00
Towing	80.00

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer	Gross Total (\$\$)	13,252.25
Signature:	+ GST 7.00% (\$\$)	927.66
Date:		
	Nett Amount (\$\$)	14,179.91

This claim is handled by: LUM WEE KEAT

Generated using Merlmen e-Claims Internet Estimation & Adjusting System

DETAILS

Reference

Source:	(Last Synchronised: 10 Jun 2020)
Parts:	N/A ISUZU NPR75UH5A 5.2 D (M) (Model not available in database)
Labour:	Repairer's (Price-denominated Standard List)
Print Code:	S & H Motor Pte Ltd/YN8545Y/10/06/2020 15:20
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Rear number plate lamp	0.00	0.00	CM *30.00 F
2	1		*Front bumper	0.00	0.00	B *550.00 F
3	1		*LH front bumper bracket	0.00	0.00	B *150.00 F
4	1		*LH front bumper fog lamp	0.00	0.00	B *150.00 F
5	1		*LH head lamp	0.00	0.00	B *320.00 F
6	1		*LH signal lamp	0.00	0.00	CM *125.00 F
7	1		*LH top end garnish	0.00	0.00	CM *190.00 F
8	1		*LH outer mirror big	mi 0.00	0.00	*145.00 F
9	1		*LH outer mirror small	mi 0.00	0.00	*95.00 F
10	1		*LH outer mirror arm handle	mi 0.00	0.00	*320.00 F
11	1		*LH outer mirror cover top	0.00	0.00	mi *35.00 F
12	2		*LH outer mirror black cover top	0.00	0.00	mi *30.00 F
13	1		*Front windscreen glass	0.00	0.00	CM *850.00 F
14	1		*Front windscreen glass moulding	0.00	0.00	mi *220.00 F
15	1		*RH rear fuel tank	0.00	0.00	B *680.00 F
16	1		*RH rear fuel tank filter to check	0.00	0.00	*120.00 F
17	1		*Gearbox mounting	0.00	0.00	*115.00 F
18	1		*Gearbox mounting bracket	0.00	0.00	*160.00 F
19	1		*RH engine mounting	0.00	0.00	*145.00 F
20	1		*LH engine mounting	CM 0.00	0.00	*145.00 F
21	1		*RH engine mounting bracket to check	0.00	0.00	*170.00 F
22	1		*LH engine mounting bracket to check	0.00	0.00	*170.00 F
23	1		*Engine fan blade	0.00	0.00	*180.00 F
24	1		*Front drive cabin hinge	0.00	0.00	-

F=Franchise part.

Sub Total (S\$)	5,095.00
+ Margin on L,N Items 15.00% (S\$)	764.25
Total Parts (S\$)	5,859.25

S & H Motor Pte Ltd/YN8545Y/10/06/2020 15:20. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

Particulars	Amount
<u>Miscellaneous Items</u>	
1 Front number plate	35.00
1 Front windscreen inner rubber seal	45.00
1 Front windscreen sealant	68.00
1 IU Bracket	25.00
1 Prop shaft coupling (used)	200.00
1 Prop shaft front (used)	450.00
1 Prop shaft rear (used)	450.00
1 Rear number plate	35.00
1 Rear number plate top wood	80.00
Sub Total (\$)	1,388.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
	<u>Labour Items</u>		
1	To remove and reinstall front windscreen and conduct water leak test	New	150.00
2	To disconnect wire harness to facilitate repairs and check for damage and reconnect wiring system and check for full functionality. To focus headlamp	New	35.00
3	To repair rear cargo wood panels	New	220.00
4	To remove and replace rear fuel tank. To repair fuel tank brackets	New	80.00
5	To remove and check engine, gearbox, radiator, engine & gearbox mountings, for damage and reinstall components and check engine running functionality	New	480.00
6	To remove and check RH & LH rear suspension system and rear differential	New	380.00
7	To perform large vehicle wheel alignment	New	130.00
8	To remove front damaged parts, to jack out front panel, front body, and cut out damaged parts, to reshape and repair front panel, front grille, LH head lamp inner panel, , LH door hinge pillar, drive cabin rear windscreen panel, drive cabin hinge panel, and adjust body panel alignment	New	1,200.00
9	To reweld, and repair vehicle chassis. To remove and reinstall necessary parts to facilitate repairs	New	2,500.00
10	To spray paint affected front and inner damaged portion inclusive of preparatory works and material	New	750.00
	Gross Labour Cost (\$)		5,925.00

S & H Motor Pte Ltd/YN8545Y/10/06/2020 15:20. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	04/06/2020 17:31
Date Of Accident	01/06/2020 14:30
Exact Location Of Accident	ALONG KPE TO CTE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	YN8545Y
Insured/Policyholder	
Name Of Registered Owner	YEW HUAT SCAFFOLDING & CONSTRUCTION PTE LTD
Co Reg No	-
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-94260743
Alternative Phone No	OFFICE-94260743

Vehicle Particulars

Manufacturer	ISUZU
Model	NPR75UH5A

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	COMMERCIAL VEHICLE
------------------	--------------------


Insurance Company

Name of Insurance Company	LONPAC INSURANCE BHD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	Z19VC05002971
Cover Note Number	

Driver

Name of Driver	DEVARAJ NALLUSAMY
Work Permit No	GXXXX848N
Date Of Birth	28/02/1989
Occupation	OUTDOOR
Date Of Driving Pass	26/01/2018
Driving Experience	2 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94260743
Fax Number	
Contact Number	
EMail Address	NOEMAIL

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer attached statement.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature]

Policyholder's Signature
Date & Time:



GIAMNIC SINGAPORE FORM 5.3

DM

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

[Signature]

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	234C
Vehicle Details	
Vehicle No.:	YN8545Y
Vehicle to be Exported:	Yes
Intended Deregistration Date:	04 Jun 2020
Vehicle Make:	ISUZU
Vehicle Model:	NPR75UH5A
Primary Colour:	Green
Manufacturing Year:	2015
Engine No.:	4HK1357154
Chassis No.:	JAANPR75HF7104330
Maximum Power Output:	-
Open Market Value:	\$31,845.00
Original Registration Date:	11 Aug 2015
First Registration Date:	11 Aug 2015
Transfer Count:	0
Actual ARF Paid:	\$1,593.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	10 Aug 2025
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$5,953.00
COE Rebate Amount:	\$3,085.00
Total Rebate Amount:	\$3,085.00

The information contained herein is correct as at 04 Jun 2020

OK