

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Lonpac Insurance Bhd
300 Beach Road
#17-04/07 The Concourse
Singapore 199555

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Ong Li Li

Date: 05 Aug 2020

Preliminary Advice

Vehicle No	: YN8545Y	Accident Date	: 01/06/2020
Make	: ISUZU NPR75UH5A	Policy No.	: Z19VC05002971
Assignment Date	: 10/06/2020	Excess	: S\$700.00
Date of Inspection	: 11/06/2020	Est. Duration of Repair	: 18 days
Inspection At	: S & H Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive #07-02, Sin Ming AutoCity Singapore 575722		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front n/s & rear portion and parts claimed are consistent to the accident.
The undercarriage affected due to collision.

Repairer's Estimate (Gross)	:S\$	19,192.00 (inclusive supp)
Revised Amount	:S\$	11,846.75 (inclusive supp)
Check Items (Estimated)	:S\$	5,851.50
Total	:S\$	17,698.25

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	34,000.00
COE / PARF Rebate	:S\$	3,085.00
Salvage Value	:S\$	
Margin for Repair	:S\$	30,915.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage.
Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Supplementary amount is \$ 4,991.00.