

EFFICIENT MOTOR & ENGINEERING WORKS PTE LTD

56 LOYANG WAY # 06-07 ENTERPRISE BUILDING SINGAPORE 508775

VEHICLE NO : GBK2141G
VEHICLE & MODEL : TOYOTA HIACE VAN TURBO 51
POLICY NO : JTFHT02P000250169

DATE : 10 JUN 2020
CLAIM TYPE : TP CLAIM
D.O.A : 09 JUN 2020

INSURER : ERGO INSURANCE PTE LTD

ADJUSTMENT ON REPAIR COST & REPLACEMENT OF PARTS

S/No.	QTY	DESCRIPTION	CONDITION / REMARKS	UNIT LIST PRICE	TOTAL LIST PRICE
1	1	RH HEADLAMP ASSY / CMT		\$ 750.00	\$ 750.00
2	1	RH FRONT CORNER PANEL X R		\$ 195.00	\$ 195.00
3	1	RH SIDE MIRROR ASSY / BR		\$ 1,015.00	\$ 1,015.00
4	1	RH FRONT DOOR / DD		\$ 1,794.00	\$ 1,794.00
5	1	RH FRONT DOOR OUTER MOULDING / CMT		\$ 82.00	\$ 82.00
6	1	RH QUARTER PANEL X R / DD		\$ 1,062.00	\$ 1,062.00
7	1	RH SLIDE DOOR / DD		\$ 1,600.00	\$ 1,600.00
8	1	RH SLIDE DOOR WEATHERSTRIP ? / CMT		\$ 359.00	\$ 359.00
9	1	RH SLIDE DOOR RAIL GUIDE X NN		\$ 460.00	\$ 460.00
10	1	RH SLIDE DOOR LOCK REAR ? / BT		\$ 280.00	\$ 280.00
11	1	RH SLIDE DOOR LOCK FRONT ? / BT		\$ 145.00	\$ 145.00
12	1	RH SLIDE DOOR LOCK ACTUATOR ? / BT		\$ 145.00	\$ 145.00
13	1	RH SLIDE DOOR HANDLE INNER ? X NN		\$ 75.00	\$ 75.00
14	1	RH SLIDE DOOR LOCK FULL OPEN STOP X NN		\$ 185.00	\$ 185.00
15	1	RH SLIDE DOOR HINGE CENTER / BT		\$ 150.00	\$ 150.00
16	1	RH SLIDE DOOR ROLLER LOWER / BT		\$ 320.00	\$ 320.00
17	1	RH SLIDE DOOR ROLLER UPPER / BT		\$ 85.00	\$ 85.00
18	2	RH SLIDE DOOR STRIKER / BT		\$ 45.00	\$ 90.00
19	1	RH SLIDE DOOR STEP PANEL ? X R		\$ 1,206.20	\$ 1,206.20
20	1	RH SLIDE DOOR SCUFF PLATE X NN		\$ 180.00	\$ 180.00
21	1	RH SLIDE DOOR INNER TRIM BOARD / CMT		\$ 280.00	\$ 280.00
22	2	FRONT/REAR WHEEL HUB CAP (Front) ? X NN		\$ 180.00	\$ 360.00
23	0	0			
24	0	0			
				\$ 10,593.20	\$ 10,818.20

8112
- 25%
6084

TOTAL PRICE	\$ 10,818.20
LESS 25%	\$ 2,704.55
SUB TOTAL PRICE	\$ 8,113.65

S/No.	QTY	DESCRIPTION	CONDITION / REMARKS	UNIT S/NETT	TOTAL S/NETT
1	1	RH SLIDE DOOR TRIMBOARD CLIP SET / MC		\$ 50.00	\$ 50.00
2	1	RH FRT DOOR CO.REG STICKER / MC		\$ 30.00	\$ 30.00
3	1	SEALANT / MC		\$ 80.00	\$ 80.00

TOTAL S/NETT	90	\$ 160.00	\$ 160.00
--------------	----	-----------	-----------

Labour Charges

1	To cut & weld -damaged panels RH side portion /	\$ 1,500.00	1000 1200
	To panel beat & align door, remove & replace damaged parts.		

apply anti rust coat and Tuff Kote repaired areas	\$	100.00	60
check and rectify lighting & wiring.	\$	50.00	30
Spray painting for LH Portions, & affected areas.	\$	1,500.00	1200
To transfer slide door components. (M & P)	\$	250.00	1000 100
To do tyre balancing & wheel alignment	\$	100.00	60

TOTAL LABOUR

2650

\$ 3,500.00

Total Cost of Repairs

\$ 11,773.65

(Total parts + Total S/Nett + Total Labour Cost)

Steve CLKK)

WHL P/L

10/6/20, 1.30pm

P/P

Ry Before spy

10 days

LKK Auto Co must notify the Repairer of the following:

- To resurvey bodywork after spray painting
- To display damage after resurvey
- Parts prices are to be on a "without Prejudice" basis
- Third party surveys must be resurveyed and is subject to final approval from Insurance Company
- No illegal modifications allowed
- Supplementary work must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P- 6084

N- 90

L- 2650

P/P - 8824