

Auto Consultants
the Repairer of the following:
• To survey before/after
• To display damaged parts
• Parts prices are subject to third party survey
• No illegal modifications
• Supplementary is subject to third party survey

Acknowledged by Repairer

Vehicle No.: SMN 6178 D

Date:

YAP LEE MOTOR

Reg. No. 52910085A

1 Kaki Bukit Ave 6 #01-26 Autobay@Kaki Bukit Singapore 417883
Tel: 68441555 Fax: 68441311 Email: yap_lee_motor@singnet.com.sg

MHF 228H 3300064245 12 June 2020

Make / Model: Toyota Sienta

TP AIG
Veron

Your Reference: SLK 3458 T
AIG Asia Pacific Insurance Pte Ltd

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
	<u>LIST ITEM</u>	
1	Rear Bumper <i>Rehand</i>	788.70
1	Rear Bumper Retainer <i>RH New</i>	329.80 <i>95</i>
2	Rear Bumper Bracket <i>new</i>	375.84 <i>+</i>
1	Rear Bumper Protector (Centre) <i>new</i>	225.00 <i>+</i>
1	Rear Bumper Reflector RH <i>cracked</i>	95.00 <i>✓</i>
1	Rear Bumper Side Protector RH <i>cut</i>	280.48 <i>✓</i>
1	Rear End Panel <i>Reps</i>	820.70 <i>+</i>
1	Taillamp RH <i>cut</i>	477.25 <i>✓</i>
1	Taillamp Panel RH <i>new</i>	105.75 <i>+</i>
1	Trunlewd Lamp RH <i>new</i>	341.08 <i>+</i>
1	Rear Fender RH <i>Reps</i>	672.59 <i>+</i>
1	Rear Fender Liner RH <i>new</i>	236.74 <i>+</i>
	<i>Rear Fender Air Vent RH cracked</i>	
	<i>92 ✓</i>	\$ 4,748.93
	<i>Less 20%</i>	\$ 949.79
	<i>75%</i>	3,799.14

SPECIAL NETT ITEMS

1	Rear Bumper Clip (Set) <i>new</i>	\$ 60.00 <i>30</i>
1	Reverse Sensor <i>new</i>	\$ 350.00 <i>+</i>
1	Rear Fender Liner Clip (Set) <i>new</i>	\$ 50.00 <i>+</i>
		\$ 460.00

LABOUR CHARGES

To remove & refix reverse sensor system.	\$ 120.00 <i>50</i>
To remove & refix inner trim garnish.	\$ 120.00 <i>50</i>
To apply undercoating.	\$ 120.00 <i>50</i>
To check wiring system.	\$ 60.00 <i>30</i>
To cut, jack, remove & repair the above parts.	\$ 800.00 <i>500</i>
To re-spray on the affected areas.	\$ 1,000.00 <i>600</i>
	2,220.00

GRAND TOTAL:

6,479.14