

HIN LUNG WORKSHOP

Blk 1008 Bukit Merah Lane 3 #01-20, S'pore 159722. Tel: 68583000 Fax: 64760075
Website: www.hinlung.com.sg GST Regn. No: M2-0065859-X

Your Ref:

Page: 1

Our Ref : 0700/06/20

Date: 10/06/2020

M/s : CHINA TAIPING INSURANCE (S) PTE LTD

3 ANSON ROAD #16-00

SPRINGLEAF TOWER

SINGAPORE 079909

Attn : MOTOR CLAIMS DEPARTMENT

Dear Sir/Madam,

ACCIDENT REPAIR ON : SGM3203K - EDIX-1.7 (A) 0
INSURED : CHIN JOSEPH
DATE OF ACCIDENT : 09/06/2020
YOUR INSURED VEH NO: SKR1157A

APPENDED BELOW ARE THE ESTIMATED COST OF REPAIR & PARTS TO BE REPLACED:-

		S\$	S\$	S\$
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER <i>de</i>	1 @ 980.20	980.20	<i>1279.20</i>
2	REAR SIDE RETAINER LH <i>nee</i>	1 @ 34.00	34.00	
3	REAR SIDE RETAINER RH <i>X SVC</i>	1 @ 34.00	34.00	
4	BUMPER CLIPS <i>nee</i>	10 @ 5.50	55.00	
5	REAR FENDER LH <i>repair</i>	1 @ 1,025.00	1,025.00	<i>1023.36</i>
6	REAR FENDER RH <i>X SVC</i>	1 @ 1,025.00	1,025.00	
7	REAR END PANEL <i>repair</i>	1 @ 530.00	530.00	
8	REAR BOOT WITH WORDINGS <i>repair</i>	1 @ 1,353.00	1,353.00	
9	PANEL GARNISH LH <i>?cra</i>	1 @ 210.00	210.00	
10	LINING, FENDER LH <i>X SVC</i>	1 @ 319.00	319.00	
11	WEATHER STRIP, TAILGAYE <i>X SVC</i>	1 @ 161.00	161.00	
Total			5,726.20	

LABOUR CHARGES

- 1 REPLACE NEW PARTS, REMOVE/REFIT ALL ATTACHMENT PARTS TO FACILITATE REPAIR.
- 2 SPRAY PAINT ON THE EFFECTED AREAS WITH 2K PAINT.
- 3 CHECK WIRING AND PROPER FUNCTIONING.

Nett Total Before GST

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

1300
1023.36
1300.00
2323.36
206
1858.68
4/5-1,850

1,200.00 ~~400~~ *500*
1,000.00 ~~200~~ *800*
80.00 *X NN*
8,006.20

Rasul
Hp 90010068
6 days
4/5
12/06/2020 @ 1030