

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
 TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
 GST:201300201N

M/S : QBE INSURANCE (SINGAPORE) PTE LTD

1 RAFFLES QUAY
 #29-10 SOUTH TOWER
 SINGAPORE 048583

TEL: 62246633

FAX: 65345356

ATTN: Motor Claim Department

Estimate No: EST2000111

Date: 08 Jun 2020

Veh Reg No: SDB7323P

Make/Model: TOYOTA CAMRY 2.4
 AUTO ABS AIRBAG

Chasis No: MR053BK4007014436

Reg. Date: 27/07/2007

Your Ref No: SLX5138K

Claim Type: Third Party

Accident Date: 03/06/2020

TP Veh Reg No: SLX5138K

Ashes

Estimate Repair Cost to Vehicle No :SDB7323P

Quantity	Description	List Price	Amount
		SS	SS
List Price			
1	1 PC REAR BUMPER <i>Rebond</i>	580.50 ✓	
2	1 PC REAR BUMPER REINFORCEMENT <i>Best.</i>	442.70 ✓	361
3	1 PC REAR BUMPER REFLECTOR - LH <i>cut</i>	54.10 ✓	
4	1 PC REAR BUMPER SIDE RETAINER LH <i>new</i>	65.40 ✓	
5	1 PC REAR PANEL <i>Dented</i>	602.10 ✓	
6	1 PC REAR PANEL TRIM <i>Rebond</i>	353.80 ✓	
7	1 PC TAIL LAMP LH <i>cut</i>	416.90 ✓	
8	1 PC TAIL LAMP LOWER BRACKET LH <i>new</i>	36.70 x.	
9	1 PC BOOT LID <i>Reps</i>	863.10 ✓	
10	1 PC BOOTLID "CAMRY" EMBLEM <i>new</i>	49.60 ✓	
11	1 PC BOOT LID "TOYOTA" EMBLEM <i>new</i>	66.70 ✓	
12	1 PC BOOTLID "2.4" EMBLEM	41.20 ✓	
13	1 PC BOOT LID LAMP LH <i>new</i>	382.10 +	
14	1 PC BOOT LID RUBBER <i>cut</i>	204.60 ✓	
15	1 PC BOOTLID INNER LOCK <i>new</i>	360.40 +	
		4,519.90	
	Less 25%	1,129.98	3,389.97
Special Net			
16	1 SET REVERSE SENSORS <i>Rebond</i> <i>200</i>	250.00 ✓ <i>200.</i>	
		250.00	250.00
Labour			
17	1 TO CHECK WIRING	50.00 ✓ <i>30</i>	
18	1 TO SPRAY UNDERSEAL	150.00 ✓ <i>60.</i>	
19	1 TO REMOVE AND REFIT REVERSE SENSOR	120.00 ✓ <i>50.</i>	
20	1 (REAR) TO SPRAY PAINTING	1,000.00 ✓ <i>800</i>	
21	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	1,000.00 ✓ <i>700.</i>	

1640

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : QBE INSURANCE (SINGAPORE) PTE LTD
1 RAFFLES QUAY

#29-10 SOUTH TOWER
SINGAPORE 048583

TEL: 62246633

FAX: 65345356

ATTN: Motor Claim Department

Claim Type: Third Party

Accident Date: 03/06/2020

TP Veh Reg No: SLX5138K

Estimate No: EST2000111

Date: 08 Jun 2020

Veh Reg No: SDB7323P

Make/Model: TOYOTA CAMRY 2.4
AUTO ABS AIRBAG

Chasis No: MR053BK4007014436

Reg. Date: 27/07/2007

Your Ref No: SLX5138K


Estimate Repair Cost to Vehicle No :SDB7323P

Quantity	Description	List Price	Amount
		<u>SS</u>	<u>SS</u>
		2,320.00	2,320.00
	Total		SS 5,959.97
	Add GST @ 7%		417.20
	Total Amount Payable		<u>SS 6,377.17</u>

TOTAL: SINGAPORE DOLLAR SIX THOUSAND THREE HUNDRED SEVENTY SEVEN AND CENTS SEVENTEEN ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd


AUTHORISED SIGNATURE

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lj

1/s 08/06/20.

05 days.

total: 3936.52

1/s 3.1K.

3.1K