ASS. REC. BY:	
nneth	ASSIGNMENT
From:	
Estimated Cost:	Veh No: Sms 59476 Yr Regn: 120
QD / TP / WS / TP RES / OD RES / EVA / INV / MV	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
To Inspect Vehicle No:	Truck / Trailer or
	Make: Mondo Verel c.c 145
at Workshop m/s [ - Jui Yang of	Colour M. Brunn A/C: Insured / Std / NI / NA
	Sp.Reading 4038 T/Radio: Insured / Std / NI / NA
Insured:	Eng/No:
Policy No.	CNO: RU3 . 132433
Claims No.	Gen. Cond. 200 / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inoder / Jammed / Leaked J Burnt or
Make of Veh:	Modi: NII / S/RIm / STE A/Rim or
	Tyre Stze: F: 215/60R16
(Pollcy Condition)	R:
Remark: The veh had commenced its N/S O/S repair at the time of inspection.	1 BOT BONT EXHOUST GY I FOT LIZAT MICTORISUTPIR TSUMIT
	TOYOTYOKO or
Bal. or Market Value:	Fron! Rear
IDAC Accident Rport: Consistent?: Yes or No	R/Bal. 9 mm R/Bal. 9 mm
GIA / PR Seen: Consistent?: Yes or No	L/Bal. 9 mm L/Bal. 9 mm
Est. Repairs: 06 days Res.: Yes or No	D.O.A. 10/8/20 D.O.I. 12/8/20
um Sum: 20 % 3 Val.: Yes or No	Survey held at
A / REV / REP. / 24 HRS	Des. of Damages : Frt   Rear   O/S   N/S   U/C   Rooftop or
Vehicle: IN / OUT	
Date / Time Action / Instruction	The U/C / Chassis frame / Body Structure affected due to collision.
	DUE OF Dearly
	ays Of Renair.
: Final Report Da	Bys Of Repair:
Ħ	Survey No. of Trip: Survey Fee:
: Final Report Da	Survey No. of Trip:    Survey Fee:
Prell. Report Da   : Final Report Re   Add Fee:	Survey No. of Trip:    Survey Fee:
Final Report Da  : Final Report Re  Add Fee:	Survey No. of Trip:  Survey Fee:  Transportative  Site Insp (\$ ) _ \$ + RS \$I  Interview (\$ ); Faxyos
Prell. Report Da   : Final Report Re   Add Fee:	Survey No. of Trip:  Survey Fee:  Transportation:  Site Insp (\$ ) S+RSSI  Interview (\$ ) Fixes  Tech Invs (\$ ) Others
Final Report Da  : Final Report Re  Add Fee:	Survey No. of Trip:  Survey Fee:  Transportative:  Site Insp (\$ ) S + RSSI  Interview (\$ ) Fixtus

# 辉陽汽車有限公司

HUI YANG MOTOR PTE. LTD.

Contact Add: SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721
Tel: 64515752 (2 Lines). Fax: 64514658

GST Reg No. 201629438M

Not Norhank

11/06/2020

Owner:

SKYWAY MOTOR PTE LTD

6day, Menny After Pain

# ESTIMATE TO REPAIR HONDA VEZEL HYBRID - SMS5947G

lpc	rear tailgate	\$ 1,150.90
10pcs	rear tailgate spolier clip @\$8.00	m \$ 80.00 -
2pcs	rear tailgate hinge @\$53.60	n \$ 107.20 A
1pc	rear tailgate"HONDA" logo	√~ \$ 27.00 —
lpc	rear tailgate"VEZEL" emble	Ma \$ 55.10
1pc	rear tailgatr "HYBRID" emblem	12 \$ 68.50 <u> </u>
1 set	rear tailgate windscreen moulding	Ma \$ 68.50
1pc	rear tailgate outer garnish	mg 011 \$ 350.30 —
1pc	rear tailgate outer handle sensor	\$ 285.50 7
2pcs	rear tailgate refector @\$420.80	cm \$ 841.60 —
1pc	rear tailgate inner lock	nu \$ 198.40 -
1pc	rear tailgate inner rubber	Dis / 135.20
1pc	rear tailgate inner garnish	Bn \$ 252.70 —
1pc	rear tailgate inner handle garnish	nu \$ 20.70 —
2pcs	rear tailgate absorber @\$180.90	5 361.60 X
2pcs	rear taillamp @\$560.60	NISA \$ 1,121.20 -
2pcs	rear taillamp panel @\$156.20	\$ 312.40 7
1pc	rear bumper	By \$ 986.30 —
2pcs	rear bumper side bumper @\$195.20	\$ 390.40 7
2pcs	rear bumper side retainer @\$24.80	\$ 49.60 X
2pcs	rear bumper reflecter @\$151.50	5 303.00 X 5 530.90 —
1pc	rear end panel	<b>写</b> \$ 530.90 —
1pc	rear end panel inner garnish	Bu \$ 109.90 —
1pc	rear end panel inner sensor	\$ 195.50 <b>7</b>
1pc	rear end panel outer sensor	\$ 180.25 ?
2pcs	rear fender inner garnish @\$521.90	\$ 1,043.80 7
2pcs	rear fender protector @\$195.00	8n \$ 390.00 <u></u>
1pc	rear spare trye cardboard	\$ 350.40 X
1pc	rear spare trye inner garnish box	mg im \$ 420.80
1pc	rear spare trye lower garnish	Bn \$ 1,043.80 7 \$ 390.00 \( \sigma \) \$ 350.40 \( \times \) mg im \$ 420.80 \( \sigma \) \$ 181.90 \( \frac{7}{3} \)

less 20% balance c/f \$ 10,621.05 \$ 2,124.21 \$ 8,496.84



# 辉陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add: SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721
Tel: 64515752 (2 Lines). Fax: 64514658
GST Reg No. 201629438M

11/06/2020

Owner:

SKYWAY MOTOR PTE LTD

# ESTIMATE TO REPAIR HONDA VEZEL HYBRID - SMS5947G

balance b/f

\$ 8,496.84

1set 1set 1pc	rear reverse sensor rear number plate & casing rear parking camera	Ned Ned	s.nett s.nett s.nett	\$ \$ \$	2005A 280.00 50.00 455AL 320.00 7
	remove & refix rear windscreen glass wiring tuffkote sealant spray painting labour charges				$ \begin{array}{c ccccccccccccccccccccccccccccccccccc$



# SINGAPORE ACCIDENT STATEMENT

# **IMPORTANT NOTICE**

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

resaid.	
	ACCIDENT STATEMENT
ate Of Report	11/06/2020 13:11
ate Of Accident	10/06/2020 18:00
xact Location Of Accident	TPE PUNGGOL EXIT TOWARDS SLE
Country/State of Loss	SINGAPORE
	ETAILS OF OWN VEHICLE
Vehicle Registration Number	SMS5947G
Insured/Policyholder	
Name Of Registered Owner	SKYWAY MOTOR PTE LTD
Co Reg No	1XXXXX194N
Email Address	JENNIFER@SKYWAY.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-63336333
Vehicle Particulars	
Manufacturer	HONDA
Model	VEZEL HYBRID 1.5X AUTO
Exact Purpose for which vehicle was being used at time of accident	t en
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
Insurance Company	
Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	A28795104MCX
Cover Note Number	
Driver	
Name of Driver	NG PUI FAH @JOHNSON NG
NRIC No	SXXXX291C
Date Of Birth	09/12/1967
Occupation	INDOOR
Date Of Driving Pass	22/03/1988
Driving Experience	32 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96360818
Fax Number	
Contact Number	
EMail Address	BMW01SG@YAHOO.COM.SG

Address

16 SIMEI RISE #02-37

Postcode

528807

...

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OTHER - HIRER

Vehicle Registration Number of Driver's Own Vehicle

•

23

Insurance Company of Driver's Own Vehicle

-

# **General Information of the Accident**

Type Of Accident

**COLLISION - HEAD TO REAR** 

Weather Conditions

RAINING

Road Surface

WET

#### Other Information

Was any foreign vehicle involved in this accident?

Number of vehicles (including own vehicle)

NO

involved in the accident

2

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

NO

ambulance?

YES

Was any other material or property damaged?

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

2

NAME:

Passenger 1

: MR

GENDER: : MALE

#### **Details of Police Action**

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

### **Circumstances of Accident**

#### PLEASE REFER TO ATTACHED.

# Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Was there any audio recorded?

NO

### **DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number

CB8103M

Vehicle Make/Model/Colour

**Details Of Properties** 

PRIVATE CAR

Vehicle Category Name of Driver

LEE AH BAH

NRIC/Passport Number

SXXXX078B

Contact Number

97830724

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Page 2 of 17

# Sketch Plan Pg. 2

SKETCH PLAN

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Acrident Occuped at about 6 pm, 10/06/2020
allows TPE. Towards SLE, abt your before
RAMAGOI ROAD EXIT.
- W
It was raining at time of events slight traffic
of Runggot Road exit. I stopped Whey Car Infrom Queing to exit Runggot Road.
Guerra 10 2x11 runggot koart:
Vehicle A is SWC 594760 I View Vehicle B
ie CB BIOZVI
the state of the state of
Vehicle B knock into the back of Vehicle M
When Vehicle of Stoppers.
Course botton 18624 / Maide A douge 1 ad
Camera protige recorded. Vehicle of demaged at
tront.

DECLARATION

Date & Time:

Driver's Signature

Reporting Centre Personnel's Signature

NRIC/FIN No.:

https://docisolation.prod.fire.glass/?guid=bef06241-8909-45f7-91d3-615c757dd0ae