

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 16 Jun 2020

Preliminary Advice

Insured Vehicle No	:	GBC413C		
TP Vehicle No	:	SMB72C	Accident Date	: 06/06/2020
Make	:	MERCEDES-BENZ OC500LE1830H	Assignment Date	: 12/06/2020
Date of Inspection	:	12/06/2020	Est. Duration of Repair	: 2.00
Inspection At	:	SMRT AUTOMOTIVE SERVICES PTE LTD (WOODLANDS) 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:	\$ 3,959.20
Revised Amount	:	\$ 3,267.98
Check Items (Estimated)	:	\$ 0.00
Total	:	\$ 3,267.98
Lump Sum Repair		:

Total Loss Consideration

New for Old Value	:	\$
Pre-Accident Value	:	\$
COE / PARF Rebate	:	\$
Salvage Value	:	\$
Margin for Repair	:	\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :