

JA AUTOCARE PTE LTD

8 Kaki Bukit Ave 4
 #02-37 Premier @ Kaki Bukit
 Singapore 415875
 Tel : 94513429

Not Authorized
LL Pump & ?
Assuming After Paint
9 days

India International Insurance Pte Ltd
 64 Cecil Street
 #04/#05 IOB Building
 Singapoew 049711
 Attn: Motor Claims Department

ESTIMATE

Date: 15.06.2020
 vehicle number: SKH2785H
 Model RENAULT FLUENCE
 Chassis/Eng# :
 Accident Date : 13.06.2020

01) Boot Lid		\$	R ₁	1,950.00	✓
02) Boot lid garnish		\$	Sm	580.00	X
03) Boot lid rubber		\$	Dis/CM	280.00	502m
04) Boot lid lock assy		\$	Red	550.00	✓
05) Boot lid logo		\$	Red	75.00	✓
06) Boot lid chrome		\$	Sm	250.00	X
07) Boot FLUENCE emblem		\$	nn	220.00	X
08) Boot lid spoiler		\$	SVC	620.00	X
09) Boot reflector @\$220.00x 2	<i>n/s</i>	\$	SVC	440.00	X
10) Rear Bumper	<i>n/s</i>	\$	R ₁	1,850.00	✓
11) Rear bumper bracket @90.00x2	<i>n/s</i>	\$	Dis	180.00	✓
12) Rear bumper retainer @\$65.00 x2	<i>n/s</i>	\$	CM	130.00	✓
13) Rear bumper clips	<i>n/s</i>	\$	Red	80.00	✓
14) Rear bumper reinforcement	<i>n/s</i>	\$	R ₁	580.00	✓
15) Rear bumper sponge	<i>n/s</i>	\$	SVC	185.00	X
16) Rear bumper under garnish	<i>n/s</i>	\$	R ₁	380.00	✓
17) Rear bumper under garnish clips	<i>n/s</i>	\$	Red	80.00	✓
18) Rear bumper reflector @\$120.00 x2	<i>n/s</i>	\$	Red	240.00	✓
19) Tail lamp assy @750.00 x2	<i>n/s</i>	\$	Dis/CM	1,500.00	✓
20) Rear exhaust chrome	<i>n/s</i>	\$	Red	350.00	✓
21) Rear panel	<i>n/s</i>	\$	R ₁	1,200.00	✓
22) Rear Panel Garnish	<i>n/s</i>	\$	Red	360.00	✓
21) Rear windscreen moulding	<i>n/s</i>	\$	nn	180.50	X
		\$		12,260.50	
		\$		(1,226.05)	
		\$		11,034.45	

S/Nett

22) Reverse Sensor		\$	CM	350.00	
23) Rear number plate with casing		\$	Sm	75.00	X
		\$		425.00	

JA AUTOCARE PTE LTD

8 Kaki Bukit Ave 4
#02-37 Premier @ Kaki Bukit
Singapore 415875
Tel : 94513429

India International Insurance Pte Ltd
64 Cecil Street
#04/#05 IOB Building
Singapore 049711
Attn: Motor Claims Department

ESTIMATE

Date: 15.06.2020
vehicle number: SKH2785H
Model RENAULT FLUENCE
Chassis/Eng# :
Accident Date : 13.06.2020

Labour charges

20) To checking wiring	\$	100.00	201
21) To dismantle & refix reverse sensor	\$	120.00	501
22) To dismantle & refix rear exhaust	\$	160.00	801
22) to apply anti rust chemical	\$	100.00	801
23) To knock out dent on affected areas and renew parts	\$	1,800.00	1000
24) To putty & respray painting	\$	1,800.00	900
	\$	<u>4,080.00</u>	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Sub Total \$ 15,539.45

for JA AUTOCARE PTE LTD